

Kashf inspection center (KASHF)Generated on 19 January, 2026 • Report #2316
, 2022Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211

CONFIDENCE SCORE

83/100**Vehicle Information**

Date

19 January, 2026

Fahsy Report

2316

Organization Name

KASHF

Car Make

Ford

Car Owner Name

mr ali

Buyer Name

mr ali

Year Of Manufacturing

2022

Current Mileage


95694

VIN NO.

WF0AMAF1C1NPC82826

Plate Number

875280

**AI Summary**


Overall condition: Very Good (92.03% rating). Major findings: The vehicle shows issues with the front headlights, oil leakage from the turbo, and coolant water needing replacement. Areas needing attention: Left headlight clarity, rear tire condition, and wiper water hose. Suggested actions: Monitor the condition of the headlights, check with a specialist regarding the oil and coolant issues, and consider evaluating the rear tires.

Final Score**Final Decision**

Approved

**Market Value**

N/A

**83%**

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211




CONFIDENCE SCORE

83/100

Very Good

Overall Rating



Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Service & Maintenance History

Condition Chart	System Inspection	Very Good	Good	Bad
	Electric System	80	10	10
	AC	100	0	0
	Body and berd	76.47	23.53	0
	Chassis Condition	70	30	0
	Suspestion System	100	0	0
	engine and gear	20	40	40
	Safety system	85.71	0	14.29
	Road Test	100	0	0

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Remarks



Good



Very Good



Bad

Electric System

Inspects the battery, lights, wiring, and other electrical components to ensure proper functionality.

kashf performs detailed inspection and assessment for the electrical systems and components , thanks to the experts and BOSCH diagnostic tools The inspection covers:
Front lighting system Rear lighting systems Driver assisting systems 12V battery and alternator Car accessories

Front Headlights

- Left headlight not clear and both headlights broken

Bad

Rear lights

Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

i Battery Efficiency	Very Good
i dynamo	Very Good
i High voltage battery efficiency	N/A
i Screen and Radio	Very Good
i Horn	Very Good
i Wipers <ul style="list-style-type: none">Wiper water hose broken	Good
i Power Windows	Very Good
i Power Seats	Very Good
i Mirror test	Very Good
i Sun Roof \ Panorama	N/A

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100



AC

Checks the air conditioning system to ensure proper cooling, airflow, and overall performance.

Kashf performs detailed inspection and assessment for the Air condition and engine cooling components , thanks to the experts and BOSCH diagnostic tools The inspection covers: Air Condition and Compressor Heating system Engine cooling system Fluid leaks

 Control panel	Very Good
 Ac cooling performance	Very Good
 Heater performance	Very Good
 Ac Fan operation	Very Good
 Air conditioner performance	Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211








CONFIDENCE SCORE

83/100

Body and berd

The chassis is fully inspected for 4*4



Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

i Hood Bonnet	Good
• Hood bonnet repaint	
i front left fender	Good
• Front left fender repainted	
i front left door	Very Good
i rear left door	Very Good
i rear left fender	Very Good
i trunk door	Very Good
i Rear right fender	Very Good
i rear right door	Very Good
i front right door	Very Good
i front right fender	Good
• Front right fender repainted	
i roof	Very Good
i front bumper	Good
• Front bumper repainted	
i rear bumper	Very Good
i Front Windshield	Very Good
i Rear Windshield	Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

i Door Rubber

Very Good

i Interior Condition

Very Good

Notes :

- Body dent scratch and body repaired body paint faded

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Chassis Condition

Chassis and frame are inspected for sedan

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding joint marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding joint marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

 Front Left Chassis Dimensions <ul style="list-style-type: none">Dent on front left head chassis	Good
 Front Right Chassis Dimensions	Very Good
 Rear Left Chassis Dimensions	Very Good
 Rear Right Chassis Dimensions	Very Good
 Undercarriage condition <ul style="list-style-type: none">Stone hits under the car and lower cover broken	Good
 Front Frame <ul style="list-style-type: none">Front accident	Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

<i>i</i> Rear Frame	Very Good
<i>i</i> Right Side Frame	Very Good
<i>i</i> Left Side Frame	Very Good
<i>i</i> Upper Frame	Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Suspension System

The steering system ensures the driver can control the direction of the vehicle smoothly and safely. It includes components like the steering wheel, steering column, and linkages that connect to the wheels. sedan

Steering and Suspension systems are essential for every car , therefore Kashf performs the most important checks and inspections to assure the stability of the car and shortest braking distance using BOSCH inspection station. The inspection covers: Front shock absorbers Rear shock absorbers Steering rack and components Front and rear axles Bearing Wheels hubs Engine mounts

 Front Shock absorbers	Very Good
 Rear shock absorbers	Very Good
 Front bushings and scissors	Very Good
 Bushings and rear scissors	Very Good
 Steering Column	Very Good
 Front Cross member bumper	Very Good
 Rear Cross member bumper	Very Good
 Engine\Transmission Mounts	Very Good
 Front and rear stabilizer bars	Very Good
 Front axle condition	Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

i Rear axle case

N/A

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

engine and gear

The engine is being checked for sedan

Kashf performs detailed Power-train inspection and assessment for all types of Hybrid and Electric cars , thanks to the experts and BOSCH diagnostic tools. The inspection covers :
Onboard diagnostics High Voltage Battery efficiency and estimated lifetime Electric Motor and components 2-Way Voltage Inverter Charging System Cooling System

 Engine Performance and Efficiency	<ul style="list-style-type: none">Timing cover open before & engine oil pan open before & valve cover open before engine-86%	Good
 Engine and gearbox fault testing with inspection devices	<ul style="list-style-type: none">Air shutter grill malfunction	Good
 Fluid Leaks	<ul style="list-style-type: none">Oil leakage from turbo	Bad
 Coolant leak check	<ul style="list-style-type: none">Need to change coolant water	Bad
 Hybrid System		N/A
 Suction shaft check		N/A
 exhaust system		Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Safety system

Checks the condition and performance of the brake pads, discs, and fluid to ensure safe stopping.

When it comes to braking and safety , Kashf makes sure that every single sensor and parts in the braking system and air-bag is functioning at the perfect condition and adhere to Kashf standards. The inspection covers: SRS Component Tires Braking components Seat belts Traction system

 SRS Airbags System	Very Good
 front tire condition	Very Good
 Rear tire condition <ul style="list-style-type: none">Need to change rear tires	Bad
 Wheel nuts	Very Good
 Seat belt Condition	Very Good
 Abs System	Very Good
 Spare tire and tools	Very Good

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211




CONFIDENCE SCORE

83/100

Inspection Photos

Inspection Images



Car Images

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100



Road Test

A driving test to evaluate the vehicle's performance, handling, and overall condition on the road.

Kashf professional team performs an advanced road-test to check the engine performance, wheel alignment, transmission shifts, transaxle, clutch, brakes, weird noises and car maneuvering. Also, the team inspects the car's known issues the and technical errors found by the inspection team

 Engine performance on the road	Very Good
 Transmission performance on the road	Very Good
 Four-wheel drive system	N/A
 Front differential performance	N/A
 Rear differential performance	N/A
 Tire Road	Very Good
 Brake system	Very Good
 cruise control	Very Good
 EV/Hybrid Mode Operation	N/A

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100

Kashf inspection center (KASHF)

Generated on 19 January, 2026 • Report #2316
, 2022

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa
Main Showroom
97450666211



CONFIDENCE SCORE

83/100



All Notes

All Notes

- Left headlight not clear and both headlights broken
- Wiper water hose broken
- Hood bonnet repaint
- Front left fender repainted
- Front right fender repainted
- Front bumper repainted
- Body dent scratch and body repaired body paint faded
- Dent on front left head chassis
- Stone hits under the car and lower cover broken
- Front accident
- Timing cover open before & engine oil pan open before & valve cover open before engine-86%
- Air shutter grill malfunction
- Oil leakage from turbo
- Need to change coolant water
- Need to change rear tires