



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **PILOT**

Date : **9/7/2026**

Plate No. : **789276**

Time : **13:30**

Model : **2022** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN:5FN9F6879NB700887

42920KM

Scratches + dents on body + plastic kit + rings scratched

Rear bumper support bend & loose

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + front right fender

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

2022 Honda Vehicle Diagnostic Report

Vehicle Information

2022/Honda/Pilot/
VIN: 5FNYP6879NB700887

Customer Information

Name: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.30

Odometer Reading: 42920km
License Plate: --

Tel: --

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709124143941

System Scanned (18)

System

System	Status/DTC
Engine-PGM FI	
ACM	✓ 0
AT	✓ 0
ABS VSA	✓ 0
SRS	✗ 3
Gauges	✓ 0
TPMS	✓ 0
EVPS	✓ 0
Body electrical	✓ 0
Parking Sensor	ADAS ✗ 3
IMMOBI	✓ 0
EPS	✓ 0
Blind Spot Information	ADAS ✗ 2
Integrated Driver Support System	ADAS ✗ 1
SH-AWD/i-VTM	ADAS ✗ 2
PCU	✓ 0
Backup Control Unit	✓ 0
CAN Gateway	✓ 0
	✓ 0

DTC (11)

ABS VSA (3 DTCs)

DTC	Description	Status
U3006-17	Power Source Failure for ECU (High Voltage)	Permanent DTC
U3006-16	Power Source Failure for ECU (Low Voltage)	Permanent DTC
U0401-68	ECM Failure	Permanent DTC

Body electrical (3 DTCs)

DTC	Description	Status
U128D	Power Tailgate Control Unit lost communication with GAUGE Control Module	Permanent DTC
U0199	Lost communication with P/W (DRLOCKSW,KLDRLOCK frame)	Permanent DTC
U1281	Lost communication with MICU (MICU frame)	Permanent DTC

EPS (2 DTCs)

DTC	Description	Status
U3003-1C	12V Battery Voltage Failure	Permanent DTC
U0416-68	VSA System Malfunction	Permanent DTC

Blind Spot Information (1 DTC)

DTC	Description	Status
B1E77	Open in the right side BSI radar unit indicator circuit	Permanent DTC

Integrated Driver Support System (2 DTCs)

DTC	Description	Status
U0416-68	VSA Brake Actuator Malfunction	Permanent DTC
B2A70-12	LDW/RDM Switch Signal Circuit Short	Permanent DTC

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022 Honda Vehicle Diagnostic Report

Vehicle Information

2022/Honda/Pilot
VIN: 5FNYP6879NB700887
Path: Honda>Automatic
selection>5FNYP6879NB700887>EUROPE>Pilot>2022>Auto
scan>Engine-PGM FI>Live data

Odometer Reading: 42920 km
License Plate: --
Sub Model: EUROPE

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.30

Serial Number: VA9GR4C01193



Engine 93 %