



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة

Computerized Testing For All Kind of Cars



Car : **MG ZS**

Date : **15/8/2026**

Plate No. : **137448**

Time : **11:30**

Model : **2023** Color : **WHITE**

Type of Check : Engine +gear+chassis+paint

VIN: LSJW74U38PZ080671

46784KM

Scratches + dents on body

Service brake + service for computer codes

Please check attached diagnosis computer report

Paint:

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

Saicmg Vehicle Diagnostic Report

Vehicle Information

--/Saicmg/China/NEW MG ZS(2020)/
VIN: LSJW74U38PZ080671Odometer Reading: 46784km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815113903382

System Scanned (7)

System	Status/DTC
TCM (Transmission Control Module)-TCM (Transmission Control Module)	 2
ABS (Antilock Brake System) / SCS (Stability Control System)	 0
IPK (Instrument Pack)	 1
TPMS (Tyre Pressure Monitoring System)	 0
BCM (Body Control Module)	 2
ATC (Automatic Temperature Control)	 1
EPS (Electric Power Steering)	 1

DTC (7)

TCM (Transmission Control Module)-TCM (Transmission Control Module) (2 DTCs)

DTC	Description	Status
U010087	Lost communication with ECM	Aging
P280562	Gear sensor signal mutual check fault	Aging

IPK (Instrument Pack) (1 DTC)

DTC	Description	Status
U010087	Lost communication with ECM	Aging

BCM (Body Control Module) (2 DTCs)

DTC	Description	Status
B106673	Brake pedal switch stuck	Intermittent
U012787	Lost communication with TPMS	Intermittent

ATC (Automatic Temperature Control) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U010087	Lost communication with ECM	Intermittent
---------	-----------------------------	--------------

EPS (Electric Power Steering) (1 DTC)

DTC	Description	Status
C16B129	Electric Power Steering (EPS) assistance depend on partly enable conditions due to engine speed/power steering-ready signal unavailable	Aging

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)
VIN: LSJW74U38PZ080671
Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Trouble Codes

Odometer Reading: 46784 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193

Saicmg V8.81

Saicmg > Automatic selection > Auto scan > EMS (Engine Management System) > Trouble Codes

VC 13.8V

Trouble Codes



Trouble codes are not detected.

VIN: LSJW74U38PZ080671
Info: Saicmg/China/NEW MG ZS(2020)
SN: VA9GR4C01193

Remote Expert Vehicle Data Freeze frame Erase codes Read codes Search ESC

 VC 14% 11:40

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)

VIN: LSJW74U38PZ080671

Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Live data

Odometer Reading: 46784 km

License Plate: -

Sub Model: -

Customer Information

Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV

Version: V8.81

Serial Number: VA9GR4C01193



Engine: 92%