



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **COROLLA**

Date : **15/8/2026**

Plate No. :

Time : **13:15**

Model : **2022** Color : **WHITE**

Type of Check : Engine +gear+chassis+paint

VIN: **RKLBB0BEXN0040222**

90088KM

Change tyres + alignment

Scratches + dents on body + plastic kit

Under the car scratches by stone + timing gasket start leak

Change arm bushes + stabilizer link bushes + service brake

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + bonnet + rear right fender + front left fender

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

05/2024-03/2026 Toyota Vehicle Diagnostic Report

Vehicle Information

05//Toyota/Corolla/--
VIN: RKLBB0BEXN0040222Odometer Reading: 90088 km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.50Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815082930591

System Scanned (16)

System	Status/DTC
Engine and ECT	 1
Brake/EPB	 1
SRS airbag	 0
Combination meter	 0
Tire pressure monitor	 0
Master switch	 0
Driver door motor	 1
Right rear door motor	 0
Left rear door motor	 1
Passenger door motor	 0
Air conditioner	 0
Navigation system	 0
Cruise control	 0
EMPS	 0
Steering angle sensor (SAS)	 0
Central gateway	 0

DTC (4)

Engine and ECT (1 DTC)

DTC	Description	Status
P1603	Engine stall history	History

Brake/EPB (1 DTC)

DTC	Description	Status
C14FE14	Steering angle sensor supply voltage circuit short to ground or open	Confirmed

Driver door motor (1 DTC)

DTC	Description	Status
B2312	Master switch of driver side door fault	History

Left rear door motor (1 DTC)

DTC	Description	Status
B2312	Power window switch of left rear door fault	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

05/2024-03/2026 Toyota Vehicle Diagnostic Report

Vehicle Information

05/2024-03/2026/Toyota/Corolla
VIN: RKLBB0BEXN0040222
Path: Toyota>Automatic
selection>Corolla>Europe/Others>ZRE>Taiwan, China
Product>05/2024-03/2026>Others>With smart key>With Electrical
Park Brake>Auto scan>Engine and ECT>Live data

Odometer Reading: 90088 km
License Plate: -
Sub Model: -

Customer Information

Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV
Version: V7.50

Serial Number: VA9GR4C01193



Engine 90%