



ميونخ الذهبي لفحص السيارات ذ.م.م.

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة

Computerized Testing For All Kind of Cars



Car : **MG ZS**

Date : **15/8/2026**

Plate No. : **167257**

Time : **12:00**

Model : **2023** Color : **SILVER**

Type of Check : **Engine +gear+chassis+paint**

VIN: LSJW74U32PZ145160

48066KM

Scratches + dents on body & plastic kit

Service brake

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

Saicmg Vehicle Diagnostic Report

Vehicle Information

--/Saicmg/China/NEW MG ZS(2020)/
VIN: LSJW74U32PZ145160

Odometer Reading: 48066km

License Plate: --

Customer Information

Name: --

Tel: --


Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815120519215

System Scanned (7)

Topology



System	Status/DTC
TCM (Transmission Control Module)-TCM (Transmission Control Module)	✔ 0
ABS (Antilock Brake System) / SCS (Stability Control System)	✔ 0
IPK (Instrument Pack)	✔ 0
TPMS (Tyre Pressure Monitoring System)	✖ 4
BCM (Body Control Module)	✖ 2
ATC (Automatic Temperature Control)	✖ 1

EPS (Electric Power Steering)

 0 **DTC (7)****TPMS (Tyre Pressure Monitoring System) (4 DTCs)**

DTC	Description	Status
C1A0231	No RF signal received from left front tire sensor	Currently
C1A0331	No RF signal received from right front tire sensor	Currently
C1A0431	No RF signal received from right rear tire sensor	Currently
C1A0531	No RF signal received from left rear tire sensor	Currently

BCM (Body Control Module) (2 DTCs)

DTC	Description	Status
B106673	Brake pedal switch stuck	Intermittent
U012787	Lost communication with TPMS	Intermittent

ATC (Automatic Temperature Control) (1 DTC)

DTC	Description	Status
U010087	Lost communication with ECM	Intermittent

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)

VIN: LSJW74U32PZ145160

Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Trouble Codes

Odometer Reading: 48066 km

License Plate: --

Sub Model: --

Customer Information

Name: --


Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V8.81

Serial Number: VA9GR4C01193



Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)
VIN: LSJW74U32PZ145160
Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Live data

Odometer Reading: 48066 km
License Plate: -
Sub Model: -

Customer Information


Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193



Engine: 93%