



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **MG ZS**

Date : **15/8/2026**

Plate No. : **130275**

Time : **16:22**

Model : **2023** Color : **RED**

Type of Check : **Engine +gear+chassis+paint**

VIN: LSJW74U39PZ142899

46962KM

Change tyres + alignment

Scratches + dents on body + plastic kit + body paint damage

Rear fender two side repaired + service for AC

Change rear brake pads + service for charging system

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + all left side + rear right fender

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

Saicmg Vehicle Diagnostic Report

Vehicle Information

-/Saicmg/China/NEW MG ZS(2020)/
VIN: LSJW74U39PZ142899Odometer Reading: 46962km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815152941567

System Scanned (7)

System	Status/DTC
TCM (Transmission Control Module)-TCM (Transmission Control Module)	 0
ABS (Antilock Brake System) / SCS (Stability Control System)	 0
IPK (Instrument Pack)	 0
TPMS (Tyre Pressure Monitoring System)	 0
BCM (Body Control Module)	 6
ATC (Automatic Temperature Control)	 1
EPS (Electric Power Steering)	 0

DTC (7)

BCM (Body Control Module) (6 DTCs)

DTC	Description	Status
U012087	Lost communication with intelligent alternator	Aging
U150000	VIN mismatch with Body Control Module (BCM) or instrument pack (IPK)	Aging
B104B13	Right turn lamp drive circuit open	Aging
B106673	Brake pedal switch stuck	Intermittent
U012787	Lost communication with TPMS	Intermittent
U111687	Lost communication with Electronic Battery Sensor (EBS)	Aging

ATC (Automatic Temperature Control) (1 DTC)

DTC	Description	Status
U010087	Lost communication with ECM	Aging

Technician Notes

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)
VIN: LSJW74U39PZ142899
Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Trouble Codes

Odometer Reading: 46962 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193

Saicmg
V8.81



Saicmg > Automatic selection > Auto scan > EMS (Engine Management System) > Trouble Codes

VCA 14.2V

Trouble Codes		
DTC	Status	Description
P085111	Aging	Neutral switch signal inconsistent with CAN signal - gear N/P not engaged displayed by CAN, gear N/P engaged displayed by sensor
P085111	Aging	Park/neutral switch input circuit low

VIN: LSJW74U39PZ142899
Info: Saicmg/China/NEW MG ZS(2020)
SN: VA9GR4C01193

Remote Expert

Vehicle Data

Freeze frame

Erase codes

Read codes

Search

ESC



24% 3:22

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/NEW MG ZS(2020)
VIN: LSJW74U39PZ142899
Path: Saicmg>Automatic selection>Auto scan>EMS (Engine Management System)>Live data

Odometer Reading: 46962 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193

