



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : MAXUS T60	Date : 12/9/2026
Plate No. : 165882	Time : 10:00
Model : 2025 Color : WHITE	Type of Check : Engine+gear+chassis+paint

VIN: LSFAM11H5SA044343

24216KM

Change tyres + alignment

Scratches + dents on body + body paint damage

please check attached diagnosis computer report

Paint :

No paint on body

check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337 طريق سلوى - عين خالد - قطر
+974 66332237 مدينة مواتر - روضة راشد - قطر
+974 66332237 الخيسة - قطر
+974 40082021 خدمة العملاء

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)/
VIN: LSFAM11H5SA044343

Odometer Reading: 24216km
License Plate: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912095332758

System Scanned (7)

System	Status/DTC
EMS (Engine Management System)-Engine Management System (EMS) MT22 1 4G69	0
ABS/ESP (ABS or electronic stability program)- Electronic stability program	0
SRS (Supplemental Restraint System)	1
IC (Instrument Cluster)-Instrument Cluster (IC)	3
TPMS (Tire Pressure Monitor System)	1
BCM (Body Control Module)-BCM (Body Control Module)	0
SAS (Steering Wheel Angle Sensor)	0

DTC (5)

SRS (Supplemental Restraint System) (1 DTC)

DTC	Description	Status
U1000-16	Main power supply voltage is too low	DTC: history Lamp: off

IC (Instrument Cluster)-Instrument Cluster (IC) (3 DTCs)

DTC	Description	Status
B1117-16	Lost communication with right rear door node	DTC: history Lamp: off
U0140-87	Lost communication with left Instrument Panel (IP) node	DTC: history Lamp: off
U0128-87	Left rear Instrument Panel (IP) node controller fault	DTC: history Lamp: off

TPMS (Tire Pressure Monitor System) (1 DTC)

DTC	Description	Status
B100E-21	FL Tire Low Pressure	DTC: history Lamp: on

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)
 VIN: LSFAM11H5SA044343
 Path: MAXUS>Automatic selection>T60/XingJi L(D20)>Auto scan>Engine Management System (EMS) MT22 1 4G69>Live data

Odometer Reading: 24216 km
 License Plate: --
 Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV
 Version: V6.60
 Serial Number: VA9GR4C01193



Engine: 96%