



ميوخ الذهبى لفحص السيارات ذ.م.م.

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **COROLLA**

Date : **9/7/2026**

Plate No. : **256012**

Time : **11:30**

Model : **2023** Color : **SILVER**

Type of Check : **Engine +gear+chassis+paint**

VIN:RKLBB0BE4P0046231

83135KM

Change tyres + alignment

Scratches + dents on body + touch paint on rear bumper

Rear body door bend + front bumper loose + roof paint damage

Under the scratches by stones + facing brake disk

Please check attached diagnosis computer report

Paint :

Front bumper

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميوخ الذهبى لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03//Toyota/Corolla/-
VIN: RKLBB0BE4P0046231Odometer Reading: 83135 km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709110652034

System Scanned (18)

System	Status/DTC
Engine and ECT	 0
Brake	 2
SRS airbag	 0
Combination meter	 0
Tire pressure monitor	  0
Main body	 1
Master switch	 0
Driver door motor	 0
Right rear door motor	 0
Left rear door motor	 0
Passenger door motor	 0
Air conditioner	 0
Central gateway	 0
Steering angle sensor (SAS)	 0
EMPS	 0
Cruise control	  0
Navigation system	 0
Immobilizer	 0

DTC (3)

Brake (2 DTCs)

DTC	Description	Status
C137BA2	Brake system control module "A" system voltage system voltage low	Confirmed
C14FE14	Steering angle sensor supply voltage circuit short to ground or open	Confirmed

Main body (1 DTC)

DTC	Description	Status
B1247	Tire pressure monitor electronic control unit(ECU) lost communication	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03/2019-04/2023/Toyota/Corolla
VIN: RKLBB0BE4P0046231
Path: Toyota>Automatic
selection>Corolla>Europe/Others>ZRE>Taiwan, China
Product>03/2019-04/2023>Others>Without smart key>Without
Electrical Park Brake>Auto scan>Engine and ECT>Live data

Odometer Reading: 83135 km
License Plate: --
Sub Model: --

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43

Serial Number: VA9GR4C01193



Engine: 93%