



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : MAXUS

Date : 15/8/2026

Plate No. :

Time : 13:40

Model : 2022 Color : WHITE

Type of Check : Engine + gear + chassis + paint

VIN: LSKG5GC11NA068607

84926KM

Scratches + dents on body + plastic kit + rear right fender repaired

Bolts between engine & gearbox open before

Water hose leak + service for water circulation temperature

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + 1/4 rear body door + front left door kit

Front fender + rear door + 1/2 rear fender right side

1/2 Front fender + 1/4 front door left side

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة أثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdal Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2022 MAXUS Vehicle Diagnostic Report

Vehicle Information

2022/MAXUS/V80/V80 PLUS/
VIN: LSKG5GC11NA068607Odometer Reading: 84926km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815092053733

System Scanned (6)

System	Status/DTC
ABS/ESP (ABS or electronic stability program)- Electronic stability program	 0
SRS (Supplemental Restraint System)-Supplemental Restraint System (SRS)	 2
IC (Instrument Cluster)-Instrument Cluster (IC) 2018	 0
TPMS (Tire Pressure Monitor System)	 1
BCM (Body Control Module)-BCM (Body Control Module)	 5
SAS (Steering Wheel Angle Sensor)	 0

DTC (8)

SRS (Supplemental Restraint System)-Supplemental Restraint System (SRS) (2 DTCs)

DTC	Description	Status
B0671	System fault lamp circuit open or short to ground	DTC: pending Lamp: off
B0026	Driver Frontal Deployment Loop Open	DTC: pending Lamp: on

TPMS (Tire Pressure Monitor System) (1 DTC)

DTC	Description	Status
B2004-16	RR sensor battery voltage low	DTC: pending Lamp: on

BCM (Body Control Module)-BCM (Body Control Module) (5 DTCs)

DTC	Description	Status
B104E	Front fog lamp open or short	DTC: history Lamp: off

B104F	High beam open or short	DTC: history Lamp: off
B1050	Position light open or short	DTC: history Lamp: off
B1051	Sinciput/foot light open or short	DTC: history Lamp: off
B1062	Front wiper open or short	DTC: history Lamp: off

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022 MAXUS Vehicle Diagnostic Report

Vehicle Information

2022/MAXUS/V80/V80 PLUS

VIN: LSKG5GC11NA068607

Path: MAXUS>Automatic selection>V80/V80 PLUS>Auto scan>Engine Management System (EMS) EDC17C81 EU6>Trouble codes

Odometer Reading: 84926 km

License Plate: -

Sub Model: -

Customer Information

Name: -


Tel: -

Device Information

Scanner: MaxiSys MS909EV

Version: V6.60

Serial Number: VA9GR4C01193



2022 MAXUS Vehicle Diagnostic Report

Vehicle Information

2022/MAXUS/V80/V80 PLUS
VIN: LSKG5GC11NA068607
Path: MAXUS>Automatic selection>V80/V80 PLUS>Auto scan>Engine Management System (EMS) EDC17C81 EU6>Live data


Odometer Reading: 84926 km
License Plate: --
Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV Serial Number: VA9GR4C01193
Version: V6.60



Engine 90 %