



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : MG5

Date : 17/8/2026

Plate No. : 369780

Time : 10:00

Model : 2024 Color : RED

Type of Check : Engine +gear+chassis+paint

VIN: LSJA36E33RZ031364

85079KM

Change tyres + alignment

Scratches + dents on body + front & rear bumper loose

Under the car scratches by stones + service brake

Service for gearbox

Please check attached diagnosis computer report

Spray paint on rear body door

Paint :

1/2 rear bumper

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

Saicmg Vehicle Diagnostic Report

Vehicle Information

--/Saicmg/China/MG5/2023-/
VIN: LSJA36E33RZ031364

Odometer Reading: 85079km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260817095019143

System Scanned (6)

System	Status/DTC
ABS (Antilock Brake System) / SCS (Stability Control System)	0
SDM (Sensing Diagnostic Module)	0
IPK (Instrument Pack)	0
BCM (Body Control Module)	0
EPS (Electric Power Steering)	0
ATC (Automatic Temperature Control)	0

DTC (0)

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/MG5/2023-
VIN: LSJA36E33RZ031364
Path: Saicmg>Manual selection>China>MG5>2023->Auto
scan>TCU (Transmission Control Unit)>Trouble Codes

Odometer Reading: 85079 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193

Saicmg

V8.81

Saicmg > Manual selection > Auto scan > TCU (Transmission Control Unit) > Trouble Codes

VC 14.4V

Trouble Codes

Trouble codes are not detected.

VIN: LSJA36E33RZ031364
Info: Saicmg/China/MG5/2023-
SN: VA9GR4C01193

Remote Expert

Vehicle Data

Freeze frame

Erase codes

Read codes

Search

ESC

100%
9:52

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/MG5/2023-
VIN: LSJA36E33RZ031364
Path: Saicmg>Manual selection>China>MG5>2023->Auto
scan>EMS (Engine Management System)>Trouble Codes

Odometer Reading: 85079 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193

Saicmg
V8.81

Saicmg > Manual selection > Auto scan > EMS (Engine Management System) > Trouble Codes

VC 14.7V

Trouble Codes		
DTC	Status	Description
P013326	Aging	Upstream Oxygen Sensor Circuit Slow Response-Sensor Bilateral Aged Exceeding Lower Limit

VIN: LSJA36E33RZ031364
Info: Saicmg/China/MG5/2023-
SN: VA9GR4C01193

Remote Expert
Vehicle Data
Freeze frame
Erase codes
Read codes
Search
ESC

Saicmg Vehicle Diagnostic Report

Vehicle Information

Saicmg/China/MG5/2023-
VIN: LSJA36E33RZ031364
Path: Saicmg>Manual selection>China>MG5>2023->Auto
scan>EMS (Engine Management System)>Live data

Odometer Reading: 85079 km
License Plate: --
Sub Model: --

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V8.81

Serial Number: VA9GR4C01193



Engine 89%