



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة  
Computerized Testing For All Kind of Cars



Car : YARIS

Date : 15/8/2026

Plate No. :

Time : 14:20

Model : 2023 Color : GREY

Type of Check : Engine +gear+chassis+paint

VIN: MR2BF9C39P0026990

69674KM

Scratches + dents on body + body paint damage

Lower panel right side bend + rear body face bend & repaired

Dent on rear upper chassis

Service for gearbox shifting ( vibration )

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + rear body door + 1/4 rear left fender

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة أثناء الفحص أو بعده

\* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآثر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

# Toyota Vehicle Diagnostic Report

## Vehicle Information

--/Toyota/Yaris/--  
VIN: MR2BF9C39P0026990

Odometer Reading: --  
License Plate: --

## Customer Information

Name: --

Tel: --

## Device Information

Scanner: MaxiSys MS909EV  
Version: V7.50

Serial Number: VA9GR4C01193  
Repair Order Number:  
VA9GR4C0119320260815140634910

## System Scanned ( 11 )

| System                                   | Status/DTC |
|------------------------------------------|------------|
| EFI                                      | 0          |
| Continuously variable transmission (CVT) | 0          |
| ABS/VSC                                  | 0          |
| A/B                                      | 0          |
| Combination meter                        | 0          |
| Body                                     | 1          |
| Steering angle sensor                    | 0          |
| Electric power steering (EPS)            | 0          |
| Central gateway                          | 0          |
| Combination switch                       | 0          |
| Telematics                               | 0          |

## DTC ( 1 )

### Body ( 1 DTC )

| DTC   | Description                    | Status  |
|-------|--------------------------------|---------|
| U0155 | Meter CAN communications fault | History |

## Technician Notes

# Toyota Vehicle Diagnostic Report

## Vehicle Information

Toyota/Yaris  
VIN: MR2BF9C39P0026990  
Path: Toyota>Automatic  
selection>Yaris>Europe/Others>NGC10#>ASSB(Malaysia)  
Product>Auto scan>EFI>Live data

Odometer Reading: --  
License Plate: --  
Sub Model: --

## Customer Information

Name: --

Tel: --

## Device Information

Scanner: MaxiSys MS909EV  
Version: V7.50

Serial Number: VA9GR4C01193



Engine 92%