



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة  
Computerized Testing For All Kind of Cars



Car : **EMGRAND**

Date : **15/8/2026**

Plate No. : **912270**

Time : **15:05**

Model : **2024** Color : **TURQUOISE**

Type of Check : **Engine +gear+chassis+paint**

VIN: **LB3F31S21RG020161**

**70047KM**

Scratches + dents on body + plastic kit + front face plastic broken  
Small scratches by stone under the car

Thank you for choosing Golden Munich cars inspection

**Paint:**

Front bumper

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

\* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء



Shop: Golden Munich Cars Inspection  
Tel: 66338337  
Email: golden.munich@outlook.com  
Address: SALWA ROAD-AIN KHALED -DOHA QATAR

Report ID: MAXIA20260815094127  
Test Time: 2026-08-15 09:41:27  
Technician: --

## Emgrand Vehicle Diagnostic Report

### Vehicle Information

--/Emgrand/4th generation Emgrand/4th generation Emgrand (2023)/

VIN: LB3F31S21RG020161

### Customer Information

Name: --

### Device information

Scanner: MaxiSys MS909

Version: V5.60

Odometer Reading: --

License Plate: --

Tel: --

Serial Number: V19GM7C01221

Repair Order Number:  
V19GM7C0122120260815094114271

### System Scanned( 11 )

| System                                                                                                       | Status/DTC                                                                              |
|--------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|
| EMS (Engine Management System)-EMS (Engine Management System) - premium                                      |  0   |
| TCU (Transmission Control Unit)-TCU (Transmission Control Unit) - flagship                                   |  3   |
| ABS (AntiLock brake system)/ESP (Electronic stability program)-ESC (Electronic Stability Control) - flagship |  0 |
| SRS (Supplement Restrain System)-ACU (Airbag Control Unit) - flagship                                        |  0 |
| IPK (Instrument panel system)-IPK (Instrument Pack) - premium                                                |  1 |
| BCM (Body Control Module)-BCM (Body Control Module) - flagship                                               |  0 |
| EPS(Electronic Power Steering system)-EPS (Electric Power Steering) - flagship                               |  0 |
| MMI(Multimedia system)-MMI (Multi Media Interface) - deluxe                                                  |  0 |
| A/C (automatic air conditioning system)-AC (Air Conditioner) - premium                                       |  1 |
| GW (Gateway)                                                                                                 |  0 |
| TCM (Top Column Module)                                                                                      |  0 |

### DTC ( 5 )

TCU (Transmission Control Unit)-TCU (Transmission Control Unit) - flagship ( 3 DTCs )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|



|         |                                                   |                         |
|---------|---------------------------------------------------|-------------------------|
| P176200 | Network error,unable to get fault code definition | Read Codes/History DTCs |
| P175200 | Network error,unable to get fault code definition | Read Codes/History DTCs |
| U015587 | Network error,unable to get fault code definition | Read Codes/History DTCs |

**IPK (Instrument panel system)-IPK (Instrument Pack) - premium ( 1 DTC )**

| DTC     | Description                                       | Status                  |
|---------|---------------------------------------------------|-------------------------|
| U015687 | Network error,unable to get fault code definition | Read Codes/History DTCs |

**A/C (automatic air conditioning system)-AC (Air Conditioner) - premium ( 1 DTC )**

| DTC     | Description                                       | Status                  |
|---------|---------------------------------------------------|-------------------------|
| B118371 | Network error,unable to get fault code definition | Read Codes/History DTCs |

**Technician Notes**

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.



Shop: Golden Munich Cars Inspection  
Tel: 66338337  
Email: golden.munich@outlook.com  
Address: SALWA ROAD-AIN KHALED -DOHA QATAR

Report ID: MAXIA20260815091127

Test Time: 2026-08-15 09:41:27

Technician: --

## Emgrand Vehicle Diagnostic Report

### Vehicle Information

Emgrand/4th generation Emgrand/4th generation Emgrand (2023)

VIN: LB3F31S21RG020161

Path: Emgrand>Manual selection>4th generation Emgrand>4th generation Emgrand (2023)>Auto scan>EMS (Engine Management System) - premium>Live data

Odometer Reading: --

License Plate: --

Sub Model: --

### Customer Information

Name: --


Tel: --

### Device Information

Scanner: MaxiSys MS909

Serial Number: V19GM7C01221

Version: V5.60



Engine 92 %

