



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **GS3**

Date : **15/8/2026**

Plate No. : **725832**

Time : **12:00**

Model : **2024** Color : **WHITE**

Type of Check : Engine +gear+chassis+paint

VIN: LMWHR1G2XR1105575

72364KM

Scratches + dents on body + service for driver leather

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

GACMotor Vehicle Diagnostic Report

Vehicle Information

-/GACMotor/GS3 Power/
VIN: LMWHR1G2XR1105575Odometer Reading: --
License Plate: --

Customer Information

Name: --


Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V10.10Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815114750039

System Scanned (7)

Topology



System	Status/DTC
EMS (Engine Management System)	✓ 0
A/T (Automatic transmission)	✗ 1
BCS (Brake Control System)	✗ 1
SRS (Supplementary Restraint System)	✗ 1
EPS (Electric Power Steering)	✗ 1
RPA (Reversing Parking Aid)	✗ 1
GWM (Gateway Module)	✗ 1

ADAS

 DTC (6)**A/T (Automatic transmission) (1 DTC)**

DTC	Description	Status
U013987	Lost communication with BCM/gateway	History DTC

BCS (Brake Control System) (1 DTC)

DTC	Description	Status
U014087	CAN communication error (BCM/GWM)	History DTC

SRS (Supplementary Restraint System) (1 DTC)

DTC	Description	Status
U014687	Lost communication with gateway	History DTC

EPS (Electric Power Steering) (1 DTC)

DTC	Description	Status
U014087	GWM node communication lost	Current DTC

RPA (Reversing Parking Aid) (1 DTC)

DTC	Description	Status
U014087	Lost communication with BCM signal sent by gateway	History DTC

GWM (Gateway Module) (1 DTC)

DTC	Description	Status
U007480	Unable to check other B-CAN nodes	History DTC

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

GACMotor Vehicle Diagnostic Report

Vehicle Information

GACMotor/GS3 Power
VIN: LMWHR1G2XR1105575
Path: GACMotor>Automatic selection>Auto scan>EMS (Engine Management System)>Live data

Odometer Reading: --
License Plate: --
Sub Model: --

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V10.10

Serial Number: VA9GR4C01193



Engine: 90%