



ميونخ الذهبي لفحص السيارات ذ.م.م.

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : COROLLA

Date : 15/8/2026

Plate No. :

Time : 14:50

Model : 2023 Color : WHITE

Type of Check : Engine +gear+chassis+paint

VIN: RKLBB0BE2P0046082

62269KM

Change tyres + alignment

Scratches + dents on body + plastic kit + front right fender bend

Lower covers damage + under the car scratches by stone

Front crossmember small bend + service brake

Thank you for choosing Golden Munich cars inspection

Paint:

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآثر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

04/2023-05/2024 Toyota Vehicle Diagnostic Report

Vehicle Information

04//Toyota/Corolla/--
VIN: RKLBB0BE2P0046082

Odometer Reading: 62269 km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.50

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815143104114

System Scanned (17)

System	Status/DTC
Engine and ECT	5
Brake	1
SRS airbag	0
Combination meter	0
Tire pressure monitor	0
Main body	2
Master switch	0
Driver door motor	0
Right rear door motor	0
Left rear door motor	0
Passenger door motor	0
Air conditioner	0
Central gateway	0
Steering angle sensor (SAS)	0
EMPS	0
Cruise control	0
Immobilizer	0

ADAS

ADAS

DTC (8)

Engine and ECT (5 DTCs)

DTC	Description	Status
-----	-------------	--------

P0705	Transmission range sensor circuit (PRNDL input)	History
P1603	Engine stall history	History
P1604	Startability fault	History
P1605	Rough idling	Current
P1605	Rough idling	History

Brake (1 DTC)

DTC	Description	Status
C14FE14	Steering angle sensor supply voltage circuit short to ground or open	Confirmed

Main body (2 DTCs)

DTC	Description	Status
B1247	Tire pressure monitor electronic control unit(ECU) lost communication	History
U0126	Lost communication with steering angle sensor (SAS) module	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

04/2023-05/2024 Toyota Vehicle Diagnostic Report

Vehicle Information

04/2023-05/2024/Toyota/Corolla

VIN: RKLBB0BE2P0046082

Path: Toyota>Automatic
selection>Corolla>Europe/Others>ZRE>Taiwan, China
Product>04/2023-05/2024>Others>Without smart key>Without
Electrical Park Brake>Auto scan>Engine and ECT>Live data

Odometer Reading: 62269 km

License Plate: --

Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Serial Number: VA9GR4C01193

Version: V7.50



Engine 93%