



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **MAXUS T60**

Date : **12/9/2026**

Plate No. : **166269**

Time : **15:33**

Model : **2025** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: LSFAM11H1SA044341

15246KM

Change tyres + alignment

Scratches on body + body paint damage

Thank you for choosing Golden Munich cars Inspection

Paint:

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)/
VIN: LSFAM11H1SA044341

Odometer Reading: 15246km

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60

Serial Number: VA9GR4C01193

Repair Order Number:
VA9GR4C0119320260912151016382

System Scanned (7)

System	Status/DTC
EMS (Engine Management System)-Engine Management System (EMS) MT22 1 4G69	 0
ABS/ESP (ABS or electronic stability program)-Electronic stability program	 0
SRS (Supplemental Restraint System)	 0
IC (Instrument Cluster)-Instrument Cluster (IC)	 2
TPMS (Tire Pressure Monitor System)	 2
BCM (Body Control Module)-BCM (Body Control Module)	 0
SAS (Steering Wheel Angle Sensor)	 0

DTC (4)

IC (Instrument Cluster)-Instrument Cluster (IC) (2 DTCs)

DTC	Description	Status
U0140-87	Lost communication with left Instrument Panel (IP) node	DTC: history Lamp: off
U0128-87	Left rear Instrument Panel (IP) node controller fault	DTC: history Lamp: off

TPMS (Tire Pressure Monitor System) (2 DTCs)

DTC	Description	Status
B1010-21	RR Tire Low Pressure	DTC: history Lamp: off
U0102-87	Lost Communication With ABSESP	DTC: history Lamp: off

Technician Notes

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)
VIN: LSFAM11H1SA044341
Path: MAXUS>Automatic selection>T60/XingJi L(D20)>Auto scan>Engine Management System (EMS) MT22 1 4G69>Live data

Odometer Reading: 15246 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60

Serial Number: VA9GR4C01193



Engine 97.1