



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : MAXUS T60	Date : 12/9/2026
Plate No. : 165200	Time : 14:11
Model : 2025 Color : WHITE	Type of Check : Engine+gear+chassis+paint

VIN: LSFAM11H9SA044345

14593KM

Scratches + dents on body + plastic kit + body paint damage

Rust under the car

Thank you for choosing Golden Munich cars inspection

Paint:

No paint on body

check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337 طريق سلوى - عين خالد - قطر
+974 66332237 مدينة مواتر - روضة راشد - قطر
+974 66332237 الخيسة - قطر
+974 40082021 خدمة العملاء

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)/
VIN: LSFAM11H9SA044345Odometer Reading: 14593km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912140354491

System Scanned (7)

System	Status/DTC
EMS (Engine Management System)-Engine Management System (EMS) MT22 1 4G69	 0
ABS/ESP (ABS or electronic stability program)-Electronic stability program	 0
SRS (Supplemental Restraint System)	 0
IC (Instrument Cluster)-Instrument Cluster (IC)	 2
TPMS (Tire Pressure Monitor System)	 2
BCM (Body Control Module)-BCM (Body Control Module)	 0
SAS (Steering Wheel Angle Sensor)	 0

DTC (4)

IC (Instrument Cluster)-Instrument Cluster (IC) (2 DTCs)

DTC	Description	Status
U0123-87	SRS communication lost	DTC: history Lamp: off
U0128-87	Left rear Instrument Panel (IP) node controller fault	DTC: history Lamp: off

TPMS (Tire Pressure Monitor System) (2 DTCs)

DTC	Description	Status
B1010-21	RR Tire Low Pressure	DTC: pending Lamp: on
B1011-21	RL Tire Low Pressure	DTC: pending Lamp: on

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2025 MAXUS Vehicle Diagnostic Report

Vehicle Information

2025/MAXUS/T60/XingJi L(D20)
VIN: LSFAM11H9SA044345
Path: MAXUS>Automatic selection>T60/XingJi L(D20)>Auto scan>Engine Management System (EMS) MT22 1 4G69>Live data

Odometer Reading: 14593 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V6.60

Serial Number: VA9GR4C01193



Engine 97%