

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547


Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211

CONFIDENCE SCORE

79/100**Vehicle Information**

Date	Fahsy Report
26 June, 2025	547
Organization Name	Car Make
KASHF	Infiniti
Car Owner Name	Car Model
السادة مزاد قطر	Infiniti QX60
Buyer Name	Vehicle Color
السادة مزاد قطر	أبيض
Year Of Manufacturing	Engine Type
2020	fuel
Engine Capacity	Current Mileage
3.0	67623
VIN NO.	Plate Number
JN1EV7EK6LM340490	684107


**Car Options**

Full Electric Seat, Screen, Glass Roof, radar, maps, Cameras


Final Score

✓ Final Decision
Approved

👥 Market Value
N/A



Good



Overall Rating



Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100



Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

Service & Maintenance History

Condition Chart	System Inspection	Very Good	Good	Bad
	Electric System			
	AC			
	Body and berd			
	Chassis Condition			
	Suspestion System			
	engine and gear			
	Safety system			
	Road Test			

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

Remarks



Good



Very Good



Bad

Electric System

Inspects the battery, lights, wiring, and other electrical components to ensure proper functionality.

kashf performs detailed inspection and assessment for the electrical systems and components , thanks to the experts and BOSCH diagnostic tools The inspection covers: Front lighting system Rear lighting systems Driver assisting systems 12V battery and alternator Car accessories

 Front Headlights

Very Good

 Rear lights

Very Good

 Battery Efficiency

Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

i dynamo	Very Good
i High voltage battery efficiency	N/A
i Screen and Radio	Very Good
i Horn	Very Good
i Wipers <ul style="list-style-type: none">• Need to swap frontal spaces	Bad
i Power Windows	Very Good
i Power Seats	Very Good
i Mirror test	Very Good
i Sun Roof \ Panorama	Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

79/100



AC

Checks the air conditioning system to ensure proper cooling, airflow, and overall performance.

Kashf performs detailed inspection and assessment for the Air condition and engine cooling components , thanks to the experts and BOSCH diagnostic tools The inspection covers: Air Condition and Compressor Heating system Engine cooling system Fluid leaks

<i>i</i> Control panel	Very Good
<i>i</i> Ac cooling performance	Very Good
<i>i</i> Heater performance	Very Good
<i>i</i> Ac Fan operation	Very Good
<i>i</i> Air conditioner performance	Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211








CONFIDENCE SCORE

79/100



Body and berd

The chassis is fully inspected for coupe



Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

79/100

i Hood Bonnet	Very Good
i front left fender	Very Good
i front left door	Very Good
i rear left door	N/A
i rear left fender	Very Good
i trunk door <ul style="list-style-type: none"> Paint the trunk door 	Good
i Rear right fender <ul style="list-style-type: none"> Dyeing a right rear fender 	Good
i rear right door	N/A
i front right door <ul style="list-style-type: none"> Yemen front door paint 	Good
i front right fender <ul style="list-style-type: none"> Dyeing a right front flap 	Good
i roof	Very Good
i front bumper <ul style="list-style-type: none"> Dyeing Saddam in front of me 	Good
i rear bumper <ul style="list-style-type: none"> Rear bumper molding 	Good
i Front Windshield	Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

 Rear Windshield

Very Good

 Door Rubber

Very Good

 Interior Condition

Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100



Chassis Condition

Chassis and frame are inspected for sedan

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

i Front Left Chassis Dimensions	Very Good
i Front Right Chassis Dimensions <ul style="list-style-type: none"> Head dents / measurements are intact 	Good
i Rear Left Chassis Dimensions <ul style="list-style-type: none"> Left rear chassis measurements are intact / there is a ding in the head 	Good
i Rear Right Chassis Dimensions <ul style="list-style-type: none"> Rear right rear chassis measurements Minor deflection/molded repaired 	Good
i Undercarriage condition <ul style="list-style-type: none"> There's gravel hitting the bottom of the car Broken tire under the car 	Good
i Front Frame <ul style="list-style-type: none"> A blow to the front end 	Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

- i** **Rear Frame**
 - Backstroke + Bodhi modification

Good

- i** **Right Side Frame**

Very Good

- i** **Left Side Frame**

Very Good

- i** **Upper Frame**

Very Good

Notes :

- Drab Bodhi Outside

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

79/100



Suspension System

The steering system ensures the driver can control the direction of the vehicle smoothly and safely. It includes components like the steering wheel, steering column, and linkages that connect to the wheels. sedan

Steering and Suspension systems are essential for every car , therefore Kashf performs the most important checks and inspections to assure the stability of the car and shortest braking distance using BOSCH inspection station. The inspection covers: Front shock absorbers Rear shock absorbers Steering rack and components Front and rear axles Bearing Wheels hubs Engine mounts

i Front Shock absorbers	Very Good
i Rear shock absorbers	Very Good
i Front bushings and scissors	Very Good
i Bushings and rear scissors	Very Good
i Steering Column	Very Good
i Front Cross member bumper	Very Good
i Rear Cross member bumper	Very Good
i Engine\Transmission Mounts	Very Good
i Front and rear stabilizer bars <ul style="list-style-type: none"> Need rear stabilizer bars 	Good
i Front axle case	Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547


Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

 Rear axle case

Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100



engine and gear

The engine is being checked for sedan

Kashf performs detailed Power-train inspection and assessment for all types of Hybrid and Electric cars , thanks to the experts and BOSCH diagnostic tools. The inspection covers : Onboard diagnostics High Voltage Battery efficiency and estimated lifetime Electric Motor and components 2-Way Voltage Inverter Charging System Cooling System

i Engine Performance and Efficiency	Very Good
i Engine and gearbox fault testing with inspection devices	Good
i Fluid Leaks	Very Good
i Coolant leak check	Very Good
i Hybrid System	N/A
i Suction shaft check	Very Good

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

79/100



Safety system

Checks the condition and performance of the brake pads, discs, and fluid to ensure safe stopping.

When it comes to braking and safety , Kashf makes sure that every single sensor and parts in the braking system and air-bag is functioning at the perfect condition and adhere to Kashf standards. The inspection covers: SRS Component Tires Braking components Seat belts Traction system

i SRS Airbags System	Very Good
i front tire condition <ul style="list-style-type: none">Front tire expiration	Good
i Rear tire condition <ul style="list-style-type: none">Rear tire expiration	Good
i Wheel nuts	Very Good
i Seat belt Condition	Very Good
i Abs System	Very Good
i Spare tire and tools <ul style="list-style-type: none">there is no	N/A

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100

Inspection Photos

Inspection Images



Car Images



Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE










79/100



Road Test

A driving test to evaluate the vehicle's performance, handling, and overall condition on the road.

Kashf professional team performs an advanced road-test to check the engine performance, wheel alignment, transmission shifts, transaxle, clutch, brakes, weird noises and car maneuvering. Also, the team inspects the car's known issues and technical errors found by the inspection team

 Engine performance on the road	Very Good
 Transmission performance on the road	Very Good
 Four-wheel drive system	Very Good
 Front differential performance	Very Good
 Rear differential performance	Very Good
 Tire Road	Very Good
 Brake system	Very Good
 cruise control	Very Good
 EV/Hybrid Mode Operation	N/A

Kashf inspection center (KASHF)

Generated on 26 June, 2025 • Report #547

Infiniti QX60 , 2020

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE

79/100



All Notes

All Notes

Wear and Tear

- Need to change the engine oil and filter
- Need to swap frontal spaces
- Paint the trunk door
- Dyeing a right rear fender
- Yemen front door paint
- Dyeing a right front flap
- Dyeing Saddam in front of me
- Rear bumper molding
- Head dents / measurements are intact
- Left rear chassis measurements are intact / there is a ding in the head
- Rear right rear chassis measurements Minor deflection/molded repaired
- There's gravel hitting the bottom of the car Broken tire under the car
- A blow to the front end
- Backstroke + Bodhi modification
- Drab Bodhi Outside
- Need rear stabilizer bars
- Front tire expiration
- Rear tire expiration
- there is no
- Need to change the engine oil and filter