



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : SUNNY	Date : 16-05-26
Plate No. : 867235	Time : 4:30 PM/131951KM
Model : 2022 Color : WHITE	Type of Check : full check+paint

CHASSI: MDHBN7AD5NG138913			SCANNER CHECKED
	front	rear	center
right	OK	OK	OK
left	OK	OK	OK

Engine-Gear-Diffrentiell:

Engine:86% service vlave lifter+oil pump+service engine+change engine mounting
timing chain gasket leak+change engine belt & bearing tensioner

Gear: OK change gear box mounting

Diffrentiell:OK

Body -Suspension-Notes:

body+kit plastik scratch+dent+change tyre+ailgnment+bonnet bend

rear face repaired+bend+over hall front suspension+change rear shock absorber

march r.side repaired+under the car+under chassi scratch+service exhasut

water wash cup cancel+service brake

Paint:

kit plastik+rear body door+1/2 march+1/2 front door r.side

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : SUNNY	Date : 16-05-26
Plate No. : 867235	Time : 4:30 PM/131951KM
Model : 2022 Color: WHITE	Type of Check : فحص شامل+صبيغ

فحص الاسكانر	CHASSI: MDHBN7AD5NG138913			
	وسط	خلفي	امامي	
	OK	OK	OK	يمين
	OK	OK	OK	يسار

مكيئة+جير+دفرنش:

مكيئة:86% سيرفس لفر الصبايات+طرمة الزيت+سيرفس المكيئة+تبديل كراسي المكيئة
كسكيت صدر المكيئة ليك+تبديل سير المكيئة مع اليرنجات
جير: OK تبدل كرسي الجير

دفرنشات: OK

البدي-بوشات-ملاحظات:

البدي+كيت بلاستك مجرحين+نقرات+تبديل توارير+ميزانية+البانة مطعوجة
الواجهة الخلفية معدلة+مطعوجة+صيانة للهيئة الامامية+تبديل جنبينات خلفية
المارش يمين معدل+حكات في بطن السيارة+بطن الشاصي+سيرفس الاكروست
غطاء تنك المساحات مكنسل+سيرفس بريك

صبيغ:

كيت بلاستك+باب الشنطة+نصف المارش+نصف باب امامي يمين

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره
* Center is not responsible for any damage may show car.

