



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : MAZDA-6	Date : 18-05-26
Plate No. : 398557	Time : 6:37 pm 111097KM
Model : 2022 Color : SILVER	Type of Check : full check+paint

CHASSI: JM7GL4S36N1466690

	front	rear	center	scanner check
right	OK	OK	OK	
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine:87% rear engine oil seal+engine crankic gasket oil seal small leak+timing chain gasket small leak
service valve lifter+oil pump+service engine+change engine mounting

Gear: OK change gear box mounting

Differential:OK

Body -Suspension-Notes:

body+kit plastic scratch+small dent+rear bumper plastic bend+paint damage

front glass small sand damage+under the car cover broken+rear fander r.side repair

canter under exhoust safty bend+over holl front suspension

canter under chassi l.side on exhoust safty bolt dent

Paint:

kit plastic+rear fander r.side+rear door r.side

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : MAZDA-6	Date : 18-05-26
Plate No. : 398557	Time : 6:37 pm 111097KM
Model : 2022 SILVER	Type of Check : فحص شامل+صبغ

شاصي: JM7GL4S36N1466690				
فحص الاسكانر	وسط	خلفي	امامي	
	OK	OK	OK	يمين
	OK	OK	OK	يسار

مكينة+جير+دفرنش:

مكينة: 87% صوفة المكينة الخلفية + صوفة كسكيت كرنكيس المكينة ليك + كسكيت صدر المكينة ليك بسيط

سيرفس لفر الصبايات + طرمبة الزيت + سيرفس للمكينة + تبديل كراسي المكينة

جير: OK تبديل كرسي الجير

دفرنشات: OK

البيدي-بوشات-ملاحظات:

البيدي + كيت بلاستيك مجرحين + منقرين بسيط + صدام بلاستيك خلفي مطعوج + صبغه مضرب

زجاج امامي مضرب عج بسيط + كفر اسفل السيارة مكسور + رفر خلفي يمين معدل

بطن كفر سيفتي الاكزوست الوسطي مطعوج + صيانة للهيئة الامامية

بطن شاصي وسطي يسار مكان برغي سيفتي الاكزوست مخزوق

صبغ:

كيت بلاستيك + رفر خلفي يمين + باب خلفي يمين

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823