



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : NISSAN SUNNY	Date : 17-05-26
Plate No. : 615814	Time : 9:25 pm 174308KM
Model : 2020 Color : WHITE	Type of Check : full check+paint

CHASSI: MDHBN7AD4LG722846				scanner check
	front	rear	center	
right	OK	head chassi liner bend	OK	
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine:88% service valve lifter+oil pump+service engine+change engine oil+filter

bearing tensorer make sound+timing chain cover gasket starting leak

Gear: OK

Differential:OK

Body -Suspension-Notes:

body+kit plastic scratch+small dent+front bumper plastic broken

front glass small broken+rear body face bend+body r.side repair

under the car+under chassi damage by stone+change tyre+ailgnmnet

change front axle boot+service axle+service exhosut

over holl front suspension+change rear shock absorbar

Paint:

kit plastic+rear fander l.side+rear body door+all r.side

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car :	NISSAN SUNNY	Date :	17-05-26
Plate No. :	615814	Time :	9:25 pm 174308KM
Model :	2020	Color :	WHITE
		Type of Check :	فحص شامل+صبغ

شاصي: MDHBN7AD4LG722846			
فحص الاسكانر	وسط	خلفي	امامي
	OK	حرف راس شاصي مطعوج	OK
	OK	OK	OK
			يسار

مكينة+جير+دفرنش:

مكينة:88% سيرفيس لغفر الصبوبات+طرمة الزيت+سيرفيس للمكينة+تبديل زيت+فلتر المكينة
يوجد صوت في برنج مشد سير المكينة+كسكيت صدر المكينة بداية ليك

جير: OK

دفرنشات: OK

البدي-بوشات-ملاحظات:

البدي+كيت بلاستيك مجرحين+منقرين بسيط+صدام بلاستيك امامي مكسور

زجاج امامي مكسور بسيط+واجهة الشنطة مطعوجة+البدي يمين معدل

اسفل السيارة+اسفل الشاصي مضرين بالحصي+تبديل نواير+ميزانية

تبديل ربله اكسل امامي+سيرفيس الاكسلات+سيرفيس الاكزوست

صيانة للهيئة الامامية+تبديل جنبينات خلفية

صبغ:

كيت بلاستيك+رغرف خلفي يسار+باب الشنطة+جنب يمين كامل

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823