



# اف بي جي الالماني

## FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات  
Computerized Testing For All Kinds of Cars

Car : YARIS	Date : 21-06-26
Plate No. : 147159	Time : 12:55 PM/152283KM
Model : 2021 Color : WHITE	Type of Check : full check+paint

CHASSI: MHFB29F3XM2132691				NOTS
	front	rear	center	
right	OK	OK	OK	OK
left	OK	OK	OK	

### Engine-Gear-Diffrentiell:

Engine:92% change engine mounting+change bearing tensioner+service valve lifter+oil pump+tun-up engine

Gear: OK change gear box mounting

Diffrentiell:OK

### Body -Suspension-Notes:

body+kit plastik scratch+small dent+rear door l.side bend+under the car cover broken

upper tyre cover l.side broken+rear body face liner bend+march l.side bend+change brake pads

corner front bumper l.side bend+front fender r.side+2.door r.side bend+service tyre sensor

service exhasut+front light l.side damage+change front control arm bush

under the car small damage by stone

### Paint:

kit plastik+rear body door+all left side

\* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

\* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



# اف بي جي الالماني

## FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات  
Computerized Testing For All Kinds of Cars

Car : YARIS	Date : 21-06-26
Plate No. : 147159	Time : 12:55 PM/152283KM
Model : 2021 Color: WHITE	Type of Check : فحص شامل+صينغ

ملاحظة	CHASSI: MHFB29F3XM2132691			
	وسط	خلفي	امامي	
OK	OK	OK	OK	يمين
	OK	OK	OK	يسار

**مكيئة+جير+دفرنش:**

مكيئة:92% تبديل كراسي المكيئة+تبديل بيرنج مشد سير المكيئة+سيرفس لفتر الصبايات+طرمبة الزيت+نصفية للمكيئة

جير: OK تبديل كرسي الجير

دفرنشات: OK

**البدي-بوشات-ملاحظات:**

البدي+كيت بلاستيك+مجرحين+نقرات بسيطة+باب خلفي يسار مطعوج+كفر اسفل السيارة مكسور

كفر اعلى التاير يسار مكسور+حرف واجهة البدّي الخلفي مطعوج+المارش يسار مطعوج+تبديل سفائف

زاوية الصدام الامامي يسار مطعوجة+رفرف امامي يمين+باب عدد 2 يمين مطعوجين+سيرفس سنسر التواير

سيرفس الاكزوست+ضوء امامي يسار مضرب+تبديل بوشات اذرعة امامية

بطن السيارة مضرب بسيط بالحصى

**صينغ:**

كيت بلاستيك+باب الشنطة+جنب يسار كامل

\* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

\* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823