



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : TOYOTA HILUX	Date : 20-06-26
Plate No. : 239491	Time : 11:27 am 306384KM
Model : 2021 Color : WHITE	Type of Check : full check+paint

CHASSI: MR0DB9CD4M4985417

	front	rear	center	nots
right	OK	OK	OK	OK
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine:86% service valve lifter+oil pump+tun-up engine+change engine mounting

Gear: OK change gear box mounting

Differential:OK

Body -Suspension-Notes:

body+kit plastic scratch+small dent+rear light r.side small broken

under the car cover bend+bolt not complet+under the car rust

rear iron bumper small bend+saft diesel tank plastic cover broken

front glass sand damage+service tyre sensor+service ABS+USP

service exhoust+change tyre+ailgnment+over holl front suspension+rear

service head brake+service brake+spray paint on bumper

Paint:

no body paint

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : TOYOTA HILUX	Date : 20-06-26
Plate No. : 239491	Time : 11:27 am 306384KM
Model : 2021 Color : WHITE	Type of Check : فحص شامل+صينغ

شاصي: MR0DB9CD4M4985417				
ملاحظة	وسط	خلفي	امامي	
OK	OK	OK	OK	يمين
	OK	OK	OK	يسار

مكيينة+جير+دفرنش:

مكيينة: 86% سيرفس لفتنر الصبايات+طرمة الزيت+تصفية للمكيينة+تبديل كراسي المكيينة

جير: OK تبدل كرسي الجير

دفرنشات: OK

البدي-بوشات-ملاحظات:

البدي+كيت بلاستك مجرحين+منقرين بسيط+ضوء خلفي يمين مكسور بسيط

كفر اسفل السيارة مطعوج+البراغي ناقص+حلا اسفل السيارة

صدام حديد خلفي مطعوج بسيط+بلاستك كفر سيقتي تنك البترول مكسور

زجاج امامي مضرب عج+سيرفس سنسر التواير+سيرفس ABS+USP

سيرفس الاكزوست+تبدل تواير+ميزانية+صيانة للهيئة الامامية+الخلفية

سيرفس هاند بريك+سيرفس بريك+الصدام مرشوش طلاء

صينغ:

لا يوجد صينغ في البدّي

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823