



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : ACCENT	Date : 20-06-26
Plate No. : 703193	Time : 8:00 PM/204382KM
Model : 2021 Color : WHITE	Type of Check : check+paint

CHASSI: MALC741CXMM260572			SCANNER CHECKED
	front	rear	center
right	OK	head chassi bend	OK
left	OK	OK	OK

Engine-Gear-Diffrentiell:

Engine:84% service valve lifter+oil pump+tun-up engine+timing chain gasket leak+engine miss fire
engine gasket from upper+front+lower open before+service CHECK ENGINE

Gear: OK gear box bill housing open befor

Diffrentiell: differentail loose

Body -Suspension-Notes:

body+kit plastik scratch+small dent+rear fender l.side bend+service exhasut

no cover under the car+front glass small broken+rear body face bend+change battery

change rear brake pads+change rear shock absorber+face brake disk+change front control arm bush

service A/C+reditor mounting bend+under the car+chassis damage by stone+change tyre+ailgnment

Paint:

kit plastik+2.door l.side+rear body door

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره
* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر
Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : ACCENT	Date : 20-06-26
Plate No. : 703193	Time : 8:00 PM/204382KM
Model : 2021 Color: WHITE	Type of Check : فحص شامل+صينغ

فحص الاسكانر	CHASSI: MALC741CXMM260572			
	وسط	خلفي	امامي	
	OK	راس الشاصي مطعوج	OK	يمين
	OK	OK	OK	يسار

مكيينة+جير+دفرنش:

مكيينة:84% سيرفس لفر الصبابات+طرمة الزيت+تصفية للمكيينة+كسكيت صدر المكيينة ليك+تقطيع في المكيينة

كسكيت المكيينة العلوي+الامامي+السفلي مفتوحين من قبل سيرفس CHECK ENGINE

جير: OK براغي دائر الجير مفتوحين من قبل

دفرنشات: فراغ في المجموعة المتحركة

البيدي-بوشات-ملاحظات:

البيدي+كيت بلاستيك مجرحين+نقرات بسيطة+رفرف خلفي يسار مطعوج+سيرفس الاكزوست

لايوجد كفر اسفل السيارة+زجاج امامي مكسور بسيط+واجهه البيدي الخلفي مطعوجة+تبديل بطارية

تبديل سفايف خلفية+تبديل جنبيات خلفية+سيرفس المكيف+مسح درمويلات+تبديل بوشات اذرعة الامامية

كرسي الردياتور مطعوج+اسفل السيارة+الشاصي مضرين بالحصى+تبديل توابع+ميزانة

صينغ:

كيت بلاستيك+باب عدد 2 يسار+باب الشنطة

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823