



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : HILUX	Date : 20-06-26
Plate No. : 327073	Time : 5:51 PM/327485KM
Model : 2021 Color : WHITE	Type of Check : check+paint

CHASSI: MR0JB8CD5M2106953				NOTS
	front	rear	center	
right	OK	OK	OK	OK
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine:80% engine bill housing open befor+valve cover gasket leak

service valve lifter+oil pump+tun-up engine

Gear: OK gear box bill housing open befor+change gear box mounting

Diffrentiell: diffrentiell lose

Body -Suspension-Notes:

body+kit plastik scratch+small dent+rear iron bumper bend+bolt open before

bonnet bolt open before+front glass sand damage+under the car+chassi rust

change shock absober+under the car cover small bend+service exhasut+turbo hoses leak

change tyre+ailgnment+under rear fender bend+change rear spring bush

face brake disk

Paint:

all left side+front fender r.side+kit plastik+bonnet+rear body door+roof

* المحل غير مسؤول عن اى اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : HILUX	Date : 20-06-26
Plate No. : 327073	Time : 5:51 PM/327485KM
Model : 2021 Color: WHITE	Type of Check : فحص شامل+صينغ

ملاحظة	CHASSI: MR0JB8CD5M2106953			
	وسط	خلفي	امامي	
OK	OK	OK	OK	يمين
	OK	OK	OK	يسار

مكينة+جير+دفرنش:

مكينة:80% براغي دائر المكينة مفتوحين من قبل+كسكيت غطاء الصبايات ليك

سيرفس لفتر الصبايات+طرمة الزيت+تصفية للمكينة

جير: OK براغي دائر الجير مفتوحين من قبل+تبدال كرسي الجير

دفرنشات: فراغ في المجموعة المتحركة

البدي-بوشات-ملاحظات:

البدي+كيت بلاستيك مجرحين+نقرات بسيطة+صدام الحديد الخلفي مطعوج+البراغي مفتوحين من قبل

براغي البانة مفتوحين من قبل+زجاج امامي مضرب عج+حلا اسفل السيارة+الشاصي

تبدال جنبينات+كفر اسفل السيارة مطعوج بسيط+سيرفس الاكروست+هوز التيربوليك

تبدال توابر+ميزانية+بطن الرفرف الخلفي مطعوج+تبدال بوشات الطيات الخلفية

مسح درمويلات

صينغ:

جنب يسار كامل+رفرف امامي يمين+كيت بلاستيك+البانة+باب الشنطة+السقف

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823