



ميونخ الذهبى لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **COROLLA**

Date : **9/7/2026**

Plate No. : **268655**

Time : **14:25**

Model : **2021** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN:RKLBB0BE4M0038299

81102KM

Scratches + dents on body + plastic kit + touch paint

Body paint damage + rear body door bend

Rear right fender repaired + lower cover damage

Thank you for choosing Golden Munich cars inspection

Paint:

Plastic kit + 1/2 rear body door + rear right fender

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبى لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260709140150
Test Time: 2026-07-09 14:01:50
Technician: --

03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03//Toyota/Corolla/--
VIN: RKLBB0BE4M0038299

Odometer Reading: 81102 km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709140116555

System Scanned (17)

System

Status/DTC

Engine and ECT		0
Brake		2
SRS airbag		0
Combination meter		0
Tire pressure monitor		0
Main body		1
Master switch		0
Driver door motor		0
Right rear door motor		1
Left rear door motor		1
Passenger door motor		0
Air conditioner		0
Radar cruise 1		0
EMPS		0
Steering angle sensor (SAS)		0
Central gateway		0
Immobilizer		0

DTC (5)

Brake (2 DTCs)

DTC	Description	Status
-----	-------------	--------



03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03/2019-04/2023/Toyota/Corolla
VIN: RKLBB0BE4M0038299
Path: Toyota>Automatic
selection>Corolla>Europe/Others>ZRE>Taiwan, China
Product>03/2019-04/2023>Radar cruise>Without smart
key>Without Electrical Park Brake>Auto scan>Engine and
ECT>Live data

Odometer Reading: 81102 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43

Serial Number: VA9GR4C01193



Engine 90 %