



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **YARIS**

Date : **9/7/2026**

Plate No. : **170993**

Time : **8:30**

Model : **2023** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN:MR2BF9C37P0028866

62329KM

Scratches+dents on body+front bumper broken+sun cover loose

Two doors right side bend + center left body panel dent from inside

Under the car broken+front iron bumper&radiator mounting changed

Radiator support bend on under chassis

Please check attached diagnosis computer report

Paint :

Front bumper

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

Toyota Vehicle Diagnostic Report

Vehicle Information

--/Toyota/Yaris/--
VIN: MR2BF9C37P0028866Odometer Reading: --
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709093020119

System Scanned (11)

System	Status/DTC
EFI	1
Continuously variable transmission (CVT)	1
ABS/VSC	0
A/B	0
Combination meter	0
Body	0
Steering angle sensor	0
Electric power steering (EPS)	1
Central gateway	0
Combination switch	0
Telematics	0



DTC (3)

EFI (1 DTC)

DTC	Description	Status
P1603	Engine stall	History

Continuously variable transmission (CVT) (1 DTC)

DTC	Description	Status
P0706	No input of shift position switch	History

Electric power steering (EPS) (1 DTC)

DTC	Description	Status
C1557	Overheat preventive control current limit history	History

Technician Notes

Toyota Vehicle Diagnostic Report

Vehicle Information

Toyota/Yaris
 VIN: MR2BF9C37P0028866
 Path: Toyota>Automatic
 selection>Yaris>Europe/Others>NGC10#>TMT(Thailand)
 Product>Auto scan>EFI>Live data

Odometer Reading: --
 License Plate: --
 Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV
 Version: V7.43
 Serial Number: VA9GR4C01193



Engine: 94%