



ميونخ الذهبى لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **COROLLA**

Date : **9/7/2026**

Plate No. : **449218**

Time : **16:00**

Model : **2023** Color : **WHITE**

Type of Check : Engine +gear+chassis+paint

VIN: RKLBB0BE4P0048481

65410KM

Change tyres + alignment

Scratches + dents on body front bumper broken

Rear left fender repaired

Thank you for choosing Golden Munich cars inspection

Paint :

Rear bumper + rear body door + rear left fender

check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبى لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337 طريق سلوى - عين خالد - قطر
+974 66332237 مدينة مواتر - روضة راشد - قطر
+974 66332237 الخيسة - قطر
+974 40082021 خدمة العملاء

03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03//Toyota/Corolla/--
VIN: RKLBB0BE4P0048481Odometer Reading: 65410 km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709155803113

System Scanned (18)

System		Status/DTC
Engine and ECT		 4
Brake		 1
SRS airbag		 1
Combination meter		 0
Tire pressure monitor		 0
Main body		 1
Master switch		 0
Driver door motor		 0
Right rear door motor		 0
Left rear door motor		 0
Passenger door motor		 0
Air conditioner		 0
Central gateway		 0
Steering angle sensor (SAS)		 0
EMPS		 0
Cruise control		 0
Navigation system		 0
Immobilizer		 0

DTC (7)

Engine and ECT (4 DTCs)

DTC	Description	Status
P1603	Engine stall history	Current
P1603	Engine stall history	History
P1604	Startability fault	History
P1605	Rough idling	History

Brake (1 DTC)

DTC	Description	Status
C14FE14	Steering angle sensor supply voltage circuit short to ground or open	Confirmed

SRS airbag (1 DTC)

DTC	Description	Status
B1166	Airbag electronic control unit(ECU) fault 7	History

Main body (1 DTC)

DTC	Description	Status
B1247	Tire pressure monitor electronic control unit(ECU) lost communication	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

03/2019-04/2023 Toyota Vehicle Diagnostic Report

Vehicle Information

03/2019-04/2023/Toyota/Corolla
VIN: RKLBB0BE4P0048481
Path: Toyota>Automatic
selection>Corolla>Europe/Others>ZRE>Taiwan, China
Product>03/2019-04/2023>Others>Without smart key>Without
Electrical Park Brake>Auto scan>Engine and ECT>Live data

Odometer Reading: 65410 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43

Serial Number: VA9GR4C01193



Engine: 93%