



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **HILUX**

Date : **9/7/2026**

Plate No. : **245997**

Time : **10:00**

Model : **2025** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: MROBX8CD3S2857066

41443KM

Scratches + dents onm body + body paint damage

Rear bumper bend + rust under the car & chassis

Facing brake disk + change wiper

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examonation or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260709100114
Test Time: 2026-07-09 10:01:14
Technician: --

08/2024-01/2025 Toyota Vehicle Diagnostic Report

Vehicle Information

08//Toyota/Hilux/--
VIN: MR0BX8CD3S2857066

Odometer Reading: 41443 km
License Plate: --

Customer Information

Name: --
Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.43

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709100024045

System Scanned (10)

System		Status/DTC
Engine and ECT		 0
Brake		 0
SRS airbag		 0
Combination meter		 0
Tire pressure monitor		 0
Navigation system		 0
Headlamp auto leveling		 0
Cruise control		 0
4WD		 0
Immobilizer		 0

DTC (0)

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

08/2024-01/2025 Toyota Vehicle Diagnostic Report

Vehicle Information

08/2024-01/2025/Toyota/Hilux

VIN: MR0BX8CD3S2857066

Path: Toyota>Automatic
selection>Hilux>Europe/Others>TGN>Others>Pick up>08/2024-
01/2025>Others>Without smart key>Auto scan>Engine and
ECT>Live data

Odometer Reading: 41443 km

License Plate: --

Sub Model: –

Customer Information

Name: --


Tel: --

Device Information

Scanner: MaxiSys MS909EV

Serial Number: VA9GR4C01193

Version: V7.43



Engine : 96 %