



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **GROOVE**

Date : **9/7/2026**

Plate No. : **796645**

Time : **9:30**

Model : **2023** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN:LZWADAGAXPG005394

29473KM

Scratches + dents on body & plastic kit

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

EOBD Vehicle Diagnostic Report

Vehicle Information

EOBD/ISO 15765-4(CAN)
VIN: LZWADAGAXPG005394
Path: EOBD>ISO 15765-4 (CAN)>DTC&FFD

Odometer Reading: --
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V2.20

Serial Number: VA9GR4C01193

EOBD

V2.20

EOBD > ISO 15765-4 (CAN) > DTC&FFD

VCI 14.3V

Trouble codes

Trouble codes are not detected.

VIN: LZWADAGAXPG005394
Info: EOBD/ISO 15765-4(CAN)
SN: VA9GR4C01193

Remote Expert
Vehicle Data
Freeze frame
Erase codes
Read codes
Search
ESC

VCI

44%
9:40

SGMW Vehicle Diagnostic Report

Vehicle Information

SGMW/Baojun 530/Wuling Almaz/MG Hector/Chevrolet Captiva/2020 - Odometer Reading: --
VIN: LZWADAGAXPG005394 License Plate: --
Path: SGMW>Automatic selection>Auto scan>Airbag module - nine loops>Trouble codes Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV Serial Number: VA9GR4C01193
Version: V8.60

SGMW

V8.60

SGMW > Automatic selection > Auto scan > Airbag module - nine loops > Trouble codes

VCI 14.1V

Trouble codes

DTC	Status	Description
B10E400	History	Crash Output Fault

VIN: LZWADAGAXPG005394
Info: SGMW/Baojun 530/Wuling Almaz/MG Hector/Chevrolet Captiva
SN: VA9GR4C01193

Remote Expert

Vehicle Data

Freeze frame

Erase codes

Read codes

Search

ESC

EOBD Vehicle Diagnostic Report

Vehicle Information

EOBD/ISO 15765-4(CAN)
VIN: LZWADAGAXPG005394
Path: EOBD>ISO 15765-4 (CAN)>Live data

Odometer Reading: -
License Plate: -
Sub Model: -

Customer Information


Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV
Version: V2.20

Serial Number: VA9GR4C01193



Engine: 94.7