




ميونخ الذهبي لفحص السيارات ذ.م.م.

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **GRAND I10**

Date : **9/7/2026**

Plate No. : **785196**

Time : **15:00**

Model : **2023** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN:MALB251C9PM420154

97441KM

Change tyres + alignment

Scratches + dents on body + rear left fender bend

Lower right panel bend + front bumper support bend

Front iron bumper bolts open before + oil leak from engine crankcase

Gearbox crankcase open before

Thank you for choosing Golden Munich cars inspection

Paint:

Front bumpet + bonnet + front left fender

Front fender + rear door right side

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examonation or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة موآتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

2023 Hyundai(Europe) Vehicle Diagnostic Report

Vehicle Information

2023/Hyundai(Europe)/GRAND i10(AI3)/G 1.2 MPI KAPPA
VIN: MALB251C9PM420154Odometer Reading: 97441KM
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V9.23Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709145218211

System Scanned (12)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0

DTC (0)

Technician Notes

2023 Hyundai Vehicle Diagnostic Report

Vehicle Information

2023/Hyundai/GRAND i10(AI3)/G 1.2 MPI KAPPA
VIN: MALB251C9PM420154
Path: Hyundai>Automatic selection>Hyundai(Europe)>GRAND i10(AI3)>2023>G 1.2 MPI KAPPA>Auto scan>ENG (Engine)>Live data

Odometer Reading: 97441 KM
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V9.23

Serial Number: VA9GR4C01193



Engine 911.