



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **I10**

Date : **9/7/2026**

Plate No. : **783520**

Time : **11:00**

Model : **2023** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: MALB251C1PM417894

79158KM

Change tyres + alignment

Scratches + dents on body + roof paint damage

Front right door bend

Front head chassis small dent (check company)

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

2023 Hyundai(Europe) Vehicle Diagnostic Report

Vehicle Information

2023/Hyundai(Europe)/GRAND i10(AI3)/G 1.2 MPI KAPPA
VIN: MALB251C1PM417894

Odometer Reading: 79158KM

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V9.23

Serial Number: VA9GR4C01193

Repair Order Number:
VA9GR4C0119320260709105330133

System Scanned (12)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0

DTC (0)

Technician Notes

2023 Hyundai Vehicle Diagnostic Report

Vehicle Information

2023/Hyundai/GRAND i10(AI3)/G 1.2 MPI KAPPA
 VIN: MALB251C1PM417894
 Path: Hyundai>Automatic selection>Hyundai(Europe)>GRAND i10(AI3)>2023>G 1.2 MPI KAPPA>Auto scan>ENG (Engine)>Live data

Odometer Reading: 79158 KM
 License Plate: --
 Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV
 Version: V9.23
 Serial Number: VA9GR4C01193



Engine: 91%