



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **PICANTO**

Date : **9/7/2026**

Plate No. : **876227**

Time : **10:00**

Model : **2022** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: KNAB25121NT979899

71727KM

Change tyres + alignment

Scratches + bend on body + front right fender cold repaired

Under the car scratches by stones

Please check attached diagnosis computer report

Paint :

Plastic kit + rear body door

Front right door + rear right door

Front left fender + front left door + rear left door

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337 طريق سلوى - عين خالد - قطر
+974 66332237 مدينة مواتر - روضة راشد - قطر
+974 66332237 الخيسة - قطر
+974 40082021 خدمة العملاء

2022 Kia(Europe) Vehicle Diagnostic Report

Vehicle Information

2022/Kia(Europe)/Picanto/Morning (JA)/G 1.2 MPI KAPPA
VIN: KNAB25121NT979899Odometer Reading: 71727KM
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V9.23Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260709102209424

System Scanned (9)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
I-TPMS (I-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (0)

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022 Kia Vehicle Diagnostic Report

Vehicle Information

2022/Kia/Picanto/Morning (JA)/G 1.2 MPI KAPPA
 VIN: KNAB25121NT979899
 Path: Kia>Automatic selection>Auto scan>ENG (Engine)>Live data


Odometer Reading: 71727 KM
 License Plate: --
 Sub Model: --

Customer Information

Name: -- Tel: --

Device Information

Scanner: MaxiSys MS909EV
 Version: V9.23
 Serial Number: VA9GR4C01193



Engine: 90%.