



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **PICANTO**

Date : **8/7/2026**

Plate No. : **891528**

Time : **15:00**

Model : **2022** Color : **RED**

Type of Check : **Engine +gear+chassis+paint**

VIN: KNAB25129NT942969

174245KM

Scratches + bends on body + plastic kit damage

Rear body face bend + rear bumper bolts open before

Front face sand damage + lower cover broken

Change engine oil + brake pads

Thank you for choosing Golden Munich cars inspection

Paint:

Rear body door + rear bumper

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

2022 Kia(Europe) Vehicle Diagnostic Report

Vehicle Information

2022/Kia(Europe)/Picanto/Morning (JA)/G 1.2 MPI KAPPA
VIN: KNAB25129NT942969

Odometer Reading: 174245KM

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V9.23

Serial Number: VA9GR4C01193

Repair Order Number:

VA9GR4C0119320260708145239196

System Scanned (9)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
I-TPMS (I-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022 Kia Vehicle Diagnostic Report

Vehicle Information

2022/Kia/Picanto/Morning (JA)/G 1.2 MPI KAPPA
VIN: KNAB25129NT942969
Path: Kia>Automatic selection>Auto scan>ENG (Engine)>Live data

Odometer Reading: 174245 KM
License Plate: --
Sub Model: --

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V9.23

Serial Number: VA9GR4C01193



Engine 87.1