



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **CRETA**

Date : **15/8/2026**

Plate No. : **689238**

Time : **14:12**

Model : **2024** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: **MF3PB812XRJ096553**

60522KM

Change tyres + alignment

Scratches + dents on body + plastic kit

Water thermostat leak + service for water circulation + temperature

Thank you for choosing Golden Munich cars inspection

Paint:

Rear right door

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2024 Hyundai(Europe) Vehicle Diagnostic Report

Vehicle Information

2024/Hyundai(Europe)/CRETA(SU2id)/G 1.5 MPI GAMMA II
VIN: MF3PB812XRJ096553Odometer Reading: 60522KM
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V9.30Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815135433528

System Scanned (13)

System	Status/DTC
ENG (Engine)	 0
CVT (Continuously Variable Transmission)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0

DTC (1)

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

I/M readiness status

Fault codes	Status
MIL status	OFF
DTC	0

Monitor status			Status
	MIS	Misfire monitoring	✓
	FUEL	Fuel system monitoring	✓
	CCM	Comprehensive component monitoring	✓
	CAT	Catalyst monitoring	✓
	HCAT	Heated catalyst monitoring	⊘
	EVAP	Evaporative system monitoring	⊘
	AIR	Secondary air system monitoring	⊘
	O2S	Oxygen sensor monitoring	✓
	HTR	Oxygen sensor heater monitoring	✓
	EGR	EGR system monitoring	✓

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2024 Hyundai Vehicle Diagnostic Report

Vehicle Information

2024/Hyundai/CRETA(SU2id)/G 1.5 MPI GAMMA II
VIN: MF3P8812XRJ096553

Path: Hyundai>Automatic selection>Auto scan>ENG (Engine)>Live data

Odometer Reading: 60522 KM

License Plate: --

Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V9.30

Serial Number: VA9GR4C01193



Engine 92%.