



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **YARIS**

Date: **15/8/2026**

Plate No. :

Time : **10:00**

Model : **2023** Color : **GREY**

Type of Check : Engine +gear+chassis+paint

VIN: **MR2BF9C31P0027373**

64589KM

Change tyres + alignment

Scratches + dents on body + plastic kit damage

Front iron bumper bend + under the car scratches by stones

Service brake

Please check attached diagnosis computer report

Paint:

Plastic kit

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء



Shop: Golden Munich Cars Inspection
Tel: 66338337
Email: golden.munich@outlook.com
Address: SALWA ROAD-AIN KHALED - DOHA QATAR

Report ID: MAXIA20260815102526
Test Time: 2026-08-15 10:25:26
Technician: --

Toyota Vehicle Diagnostic Report

Vehicle Information

--/Toyota/Yaris/--
VIN: MR2BF9C31P0027373

Odometer Reading: --
License Plate: --

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys MS909
Version: V5.40

Serial Number: V19GM7C01221
Repair Order Number:
V19GM7C0122120260815102506257

System Scanned(3)

System	Status/DTC
Engine and ECT	 1
ABS/VSC/TRC	 0
Combination meter	 0

DTC (1)

Engine and ECT (1 DTC)

DTC	Description	Status
P1603	Engine stall history	History

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



Vehicle Diagnostic Report

Shop Name: Golden Munich Cars Inspection
Address: SALWA ROAD- AIN KHALED - DOHA QATAR, Doha, QATAR,
Tel: 66338337 Email: golden.munich@outlook.com

Date & Time: 08/15/2026 10:26

Path:

VIN:



Engine: 95%