



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **GAC GS3**

Date : **15/8/2026**

Plate No. : **916453**

Time : **11:00**

Model : **2024** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: LMWHR1G20R1106251

76781KM

Change tyres + alignment

Scratches + dents on body + rear right door bend

Change brake pads + tune up engine + service for CHECK ENGINE

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

GACMotor Vehicle Diagnostic Report

Vehicle Information

--/GACMotor/GS3(-2020.12)/
VIN: LMWHR1G20R1106251Odometer Reading: 76781km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V10.10Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815111514894

System Scanned (13)

System	Status/DTC
EMS (Engine Management System)	 3
TCU (Dual Clutch Transmission)	 0
BCS (Brake Control System)	 1
SRS (Supplementary Restraint System)	 1
ICM (Instrument Cluster Module)	 2
BCM (Body Control System)	 4
EPS (Electric Power Steering)	 1
RPA (Reversing Parking Aid)	 1
HVAC (Heating, Ventilation and Air Conditioning)	 1
HCP (HVAC Control Panel)	 1
GWM (Gateway Module)	 1
FCP (Front Control Panel)	 2
CD (Entertainment system)	 1

ADAS

DTC (19)

EMS (Engine Management System) (3 DTCs)

DTC	Description	Status
U042600	Immobilizer authentication failed	History DTC
U116700	Immobilizer no response	History DTC
P169600	Immobilizer authentication failed (TPU)	History DTC

BCS (Brake Control System) (1 DTC)

DTC	Description	Status
-----	-------------	--------

C100118	ECU voltage too low	History DTC
---------	---------------------	-------------

SRS (Supplementary Restraint System) (1 DTC)

DTC	Description	Status
B100016	Voltage too low	History DTC

ICM (Instrument Cluster Module) (2 DTCs)

DTC	Description	Status
B180016	Terminal 30 voltage too low	History DTC
U007480	Instrument cluster in limp status	History DTC

BCM (Body Control System) (4 DTCs)

DTC	Description	Status
B1E7300	No certification request received from Engine Management System (EMS)	History DTC
B110016	Battery voltage too low	History DTC
B11B313	Brake lamp output circuit open	Current DTC
U046681	Air conditioner ambient temperature signal invalid	History DTC

EPS (Electric Power Steering) (1 DTC)

DTC	Description	Status
C160016	Battery voltage too low	History DTC

RPA (Reversing Parking Aid) (1 DTC)

DTC	Description	Status
B210016	Battery voltage low	History DTC

HVAC (Heating, Ventilation and Air Conditioning) (1 DTC)

DTC	Description	Status
B1C0016	Circuit voltage below threshold	History DTC

HCP (HVAC Control Panel) (1 DTC)

DTC	Description	Status
B2A0C16	System power supply voltage too low	History DTC

GWM (Gateway Module) (1 DTC)

DTC	Description	Status
B280016	Supply voltage too low	History DTC

FCP (Front Control Panel) (2 DTCs)

DTC	Description	Status
B2A3423	Audio MODE button fault	History DTC
B2A0016	Battery voltage too low	History DTC

CD (Entertainment system) (1 DTC)

DTC	Description	Status
-----	-------------	--------

B1B0016 Battery voltage too low

History DTC

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

GACMotor Vehicle Diagnostic Report

Vehicle Information

GACMotor/GS3(-2020.12)
VIN: LMWHR1G20R1106251
Path: GACMotor>Automatic selection>Auto scan>Engine
Management System (EMS)>Live data

Odometer Reading: 76781 km
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V10.10

Serial Number: VA9GR4C01193



Engine: 91%