



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : FUSO

Date 15/8/2026

Plate No. : 133009

Time : 16:40

Model : 2022 Color : WHITE

Type of Check : Engine +gear+chassis+paint

VIN:JL6BDE6A1NK011117

63147KM

Scratches + dents on body + body paint damage

Roof bend & small rust damage + door right side bend

Rear refrigerator broken + rear right cabin bend

Turbo hose leak + steering pump leak + service brake

Service for steering + alignment

Thank you for choosing Golden Munich cars inspection

Paint:

Front face

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء



Shop: Golden Munich Cars Inspection
Tel: 66338337
Email: golden.munich@outlook.com
Address: SALWA ROAD-AIN KHALED -DOHA QATAR

Report ID: MAXIA20260815165605
Test Time: 2026-08-15 16:56:05
Technician: --

EOBD Vehicle Diagnostic Report

Vehicle Information

EOBD/ISO 15765-4(CAN)
VIN: JL6BDE6A1NK011117
Path: EOBD>ISO 15765-4 (CAN)>DTC&FFD

Odometer Reading: --
License Plate: --
Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909
Version: V2.12

Serial Number: V19GM7C01221

EOBD
V2.12



EOBD > ISO 15765-4 (CAN) > DTC&FFD



VCb

13.8V

Trouble codes



Trouble codes are not detected.

VIN: JL6BDE6A1NK011117
Info: EOBD/ISO 15765-4(CAN)

Intelligent
diagnostics

Freeze
frame

Search

Erase
codes

Read
codes

ESC



48% 16:56





Shop: Golden Munich Cars Inspection
Tel: 66338337
Email: golden.munich@outlook.com
Address: SALWA ROAD AIN KHALED DOHA QATAR

Report ID: MAXIA20260815165605

Test Time: 2026-08-15 16:56:05

Technician: --

EOBD Vehicle Diagnostic Report

Vehicle Information

EOBD/ISO 15765-4(CAN)

VIN: JL6BDE6A1NK011117

Path: EOBD>ISO 15765-4 (CAN)>Live data

Odometer Reading: --

License Plate: --

Sub Model: --

Customer Information

Name: --


Tel: --

Device information

Scanner: MaxiSys MS909

Serial Number: V19GM7C01221

Version: V2.12



Engine: 90%

