



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **OUTLANDER**

Date : **15/8/2026**

Plate No. :

Time : **12:00**

Model : **2023** Color : **BROWN**

Type of Check : Engine +gear+chassis+paint

VIN: JE4LZU1W4PZ702766

43421KM

Scratches + dents on body + rims scratches

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اعطال قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس ماله

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2023 Mitsubishi Vehicle Diagnostic Report

Vehicle Information

2023/Mitsubishi/OUTLANDER (GF#)/
VIN: JE4LZU1W4PZ702766Odometer Reading: 43421km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V3.41Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260815115305199

System Scanned (17)

System	Status/DTC
MPI/GDI/Diesel	 0
AT/CVT/A-MT/TC-SST	 0
ABS/ASC/ASTC/WSS	 0
SRS-Air Bag	 0
Meter	 0
EPB	 0
TPMS - without KOS	 4
Air Conditioner	 0
Auto Cruise	  0
4WS/Electric Power Steering	 0
ETACS	 4
KOS/IMMO/Keyless - IMMOBI & Keyless	 4
Steering Angle Sensor	 0
AUDIO - Display Audio	 0
Corner Sensor/Sonar	 0
LIN	 1
AWC	 1

DTC (14)

TPMS - without KOS (4 DTCs)

DTC	Description	Status
-----	-------------	--------

C1932	Tire air pressure low - tire 3	Stored DTC
C1922	Tire air pressure low - tire 2	Stored DTC
C1912	Tire air pressure low - tire 1	Stored DTC
C1942	Tire air pressure low - tire 4	Stored DTC

ETACS (4 DTCs)

DTC	Description	Status
C1932	Tire air pressure low - tire 3	Stored DTC
C1922	Tire air pressure low - tire 2	Stored DTC
C1912	Tire air pressure low - tire 1	Stored DTC
C1942	Tire air pressure low - tire 4	Stored DTC

KOS/IMMO/Keyless - IMMOBI & Keyless (4 DTCs)

DTC	Description	Status
C1932	Tire air pressure low - tire 3	Stored DTC
C1922	Tire air pressure low - tire 2	Stored DTC
C1912	Tire air pressure low - tire 1	Stored DTC
C1942	Tire air pressure low - tire 4	Stored DTC

LIN (1 DTC)

DTC	Description	Status
L0734	P/W(DR) Above window position	Stored DTC

AWC (1 DTC)

DTC	Description	Status
U0431	ETACS (CAN message)	Stored DTC

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2023 Mitsubishi Vehicle Diagnostic Report

Vehicle Information

2023/Mitsubishi/OUTLANDER (GF#)
VIN: JE4LZU1W4PZ702766
Path: Mitsubishi>Automatic selection>Auto
scan>MPI/GDI/Diesel>Live data

Odometer Reading: 43421 km
License Plate: --
Sub Model: --

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V3.41

Serial Number: VA9GR4C01193



Engine: 96%