



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : NISSAN X-TRAIL	Date : 13-09-26
Plate No. :	Time : 3:54 PM 11183KM
Model : 2021 Color : WHITE	Type of Check : full check+paint

CHASSI: JN1BT2MM4MW018810

	front	rear	center	scanner check
right	OK	OK	OK	OK
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine:92% change engine oil+filter

Gear: OK

Differential:OK

Body -Suspension-Notes:

body+kit plastic scratch+dent+tyre ring scratch+under the car rust

bonnet bend+service exhoust+rear door r.side repair+change tyre+ailgnmnet

rear light from inside broken two side+rear bumper light small broken

under the car+under chassi damage by stone+change front axle boot+service axle

front fander r.side repair+service brake+rear plastic bumper repair+rear face bend

service tyre sensor+A/C vent louvers broken

Paint:

kit plastic+front fander r.side+rear door r.side+rear body door

* المحل غير مسؤول عن اى اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 50783559, 66667239 ص.ب : 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : NISSAN X-TRAIL	Date : 13-09-26
Plate No. :	Time : 3:54 PM 11183KM
Model : 2021 WHITE Color :	Type of Check : فحص شامل+صبغ

شاصي: JN1BT2MM4MW018810				
فحص الاسكانر	وسط	خلفي	امامي	
OK	OK	OK	OK	يمين
	OK	OK	OK	يسار

مكينة+جير+دفرنش:

مكينة 92% تبديل زيت+فلتر المكينة

جير: OK

دفرنشات: OK

البيدي-بوشات-ملاحظات:

البيدي+كيك بلاستيك مجرحين+منقرين+رينجات التواير مجرحة+حلا اسفل السيارة

البانة مطعوجة+سيرفس الاكزوست+باب خلفي يمين معدل+تبديل تواير+ميزانية

ضوء خلفي مكسور من الداخل جهتين+ضوء صدام خلفي مكسور بسيط

بطن السيارة+بطن الشاصي مضرين بالحصى+تبديل ريلة اكسل امامي+سيرفس الاكسلات

رفرف امامي يمين معدل+سيرفس بريك+صدام بلاستيك خلفي معدل+واجهة خلفية مطعوجة

سيرفس سنسر التواير+ريش فتحات A/C مكسورين

صبغ:

كيك بلاستيك+رفرف امامي يمين+باب خلفي يمين+باب الشنطة

* المحل غير مسؤول عن اي اعطال قد تظهر بالسيارة

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823