



ميونخ الذهبي لفحص السيارات ذ.م.م.

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : HIACE	Date : 12/9/2026
Plate No. : 300794	Time : 16:00
Model : 2020 Color : WHITE	Type of Check : Engine+gear+chassis+paint

VIN: JTFPX22P9L0093340

129741KM

Scratches + bend on body + front bumper loose

Under front left fender bend on chassis + repaired

Front chassis bend + front iron bumper support bend on head chassis

Change arm bushes + stabilizer link bushes

please check attached diagnosis computer report

Paint :

Bonnet + rear body door + center left body panel

Front fender + 1/2 front door + rear door + 1/2 rear fender right side

Front left door

check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337
+974 66332237
+974 66332237
+974 40082021

طريق سلوى - عين خالد - قطر
مدينة مواتر - روضة راشد - قطر
الخيصة - قطر
خدمة العملاء

05/2020-09/2021 Toyota Vehicle Diagnostic Report

Vehicle Information

05/2020-09/2021/Toyota/Hiace/Ventury/--
VIN: --

Odometer Reading: 129741 km

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.50

Serial Number: VA9GR4C01193

Repair Order Number:
VA9GR4C0119320260912160703815 System Scanned (6)

System	Status/DTC
Engine and ECT	 0
ABS/VSC/TRC	 0
SRS airbag	 0
Combination meter	 1
Tire pressure monitor	 1
Air conditioner	 0

 DTC (2)

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Tire pressure monitor (1 DTC)

DTC	Description	Status
C2124	Data from transmitter ID 4 not received (main)	Current

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

05/2020-09/2021 Toyota Vehicle Diagnostic Report

Vehicle Information

05/2020-09/2021/Toyota/Hiace/Ventury

VIN: --

Path: Toyota>Automatic
selection>Hiace/Ventury>Europe/Others>TRH>05/2020-
09/2021>Auto scan>Engine and ECT>Live data

Odometer Reading: 129741 km

License Plate: --

Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V7.50

Serial Number: VA9GR4C01193



Engine: 93%