



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : URVAN	Date : 12/9/2026
Plate No. : 331351	Time : 11:30
Model : 2022 Color : WHITE	Type of Check : Engine +gear+chassis+paint

VIN: JN6BE6CS3N9426758

90562KM

Scratches + dents on body + tail light broken + front glass broken

Left door + rear right fender & lower right body panel bend

Lower right body panel repaired + rear iron bumper small bend

Service for TPMS + change brake pads

Please check attached diagnosis computer report

Paint :

Rear right door + lower right body panel + 3/4 rear body door

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar
Mawater City - Rawdat Rashed - Qatar
Al Kheesa Qatar
Customer Service

+974 66338337 طريق سلوى - عين خالد - قطر
+974 66332237 مدينة مواتر - روضة راشد - قطر
+974 66332237 الخيسة - قطر
+974 40082021 خدمة العملاء

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07/Nissan/NV350 Urvan/
VIN: JN6BE6CS3N9426758

Odometer Reading: 90562km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912112726039

System Scanned (8)

System	Status/DTC
Engine	0
Transmission	0
ABS	1
Air bag	0
Meter/M&A	0
Air pressure monitor	1
BCM	0
IPDM E/R	0

DTC (2)

ABS (1 DTC)

DTC	Description	Status
C1143	Steering angle sensor circuit	Past

Air pressure monitor (1 DTC)

DTC	Description	Status
C1707	Low pressure (left rear)	Current

I/M readiness status

Fault codes	Status
MIL status	OFF
DTC	0
Monitor status	Status
MIS Misfire monitoring	

	FUEL	Fuel system monitoring	✓
	CCM	Comprehensive component monitoring	✓
	CAT	Catalyst monitoring	✓
	HCAT	Heated catalyst monitoring	⊘
	EVAP	Evaporative system monitoring	⊘
	AIR	Secondary air system monitoring	⊘
	O2S	Oxygen sensor monitoring	✓
	HTR	Oxygen sensor heater monitoring	✓
	EGR	EGR system monitoring	✓

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07-/Nissan/NV350 Urvan
VIN: JN6BE6CS3N9426758
Path: Nissan>Automatic selection>Auto scan>Engine>Live data

Odometer Reading: 90562 km
License Plate: --
Sub Model: E26

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193



Engie: 93%