



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **URVAN**

Date : **12/9/2026**

Plate No. : **19974**

Time : **11:30**

Model : **2022** Color : **WHITE**

Type of Check : Engine +gear+chassis+paint

VIN: JN6BE6CS9N9426604

120711KM

Change tyres + alignment

Scratches + dents on body + body paint damage

Roof & rear body door & lower right body panel bend

Change brake pads + service for AC + rear differential make sound

Please check attached diagnosis computer report

Paint :

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07/Nissan/NV350 Urvan/
VIN: JN6BE6CS9N9426604Odometer Reading: 120711km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912113429593

System Scanned (8)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 1
Air bag	 0
Meter/M&A	 1
Air pressure monitor	 0
BCM	 1
IPDM E/R	 1

DTC (4)

ABS (1 DTC)

DTC	Description	Status
C1143	Steering angle sensor circuit	Past

Meter/M&A (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

I/M readiness status

Fault codes

Status

MIL status

OFF

DTC

0

Monitor status

Status

	MIS	Misfire monitoring	✓
	FUEL	Fuel system monitoring	✓
	CCM	Comprehensive component monitoring	✓
	CAT	Catalyst monitoring	✓
	HCAT	Heated catalyst monitoring	⊘
	EVAP	Evaporative system monitoring	⊘
	AIR	Secondary air system monitoring	⊘
	O2S	Oxygen sensor monitoring	✓
	HTR	Oxygen sensor heater monitoring	✓
	EGR	EGR system monitoring	✓

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07-/Nissan/NV350 Urvan
VIN: JN6BE6CS9N9426604
Path: Nissan>Automatic selection>Auto scan>Engine>Live data

Odometer Reading: 120711 km
License Plate: --
Sub Model: E26

Customer Information


Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193



Engine: 92%