



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **HONDA HR-V**

Date : **12/9/2026**

Plate No. : **394512**

Time : **9:45**

Model : **2021** Color : **SILVER**

Type of Check : **Engine +gear+chassis+paint**

VIN: MRJRU5851MP010622

99769KM

Change tyres + alignment

Scratches + dents on body + rims scratches + front under fender bend

Rear fender 2 side repaired + front & rear face changed

Rear chassis bend + under the car bend

Please check attached diagnosis computer report

Paint :

Plastic kit + bonnet + rear body door

Front right fender + rear right fender

Front left fender + rear left fender

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2021 Honda Vehicle Diagnostic Report

Vehicle Information

2021/Honda/HR-V/
VIN: MRJRU5851MP010622

Odometer Reading: 99769km
License Plate: -

Customer Information

Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV
Version: V7.32

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912093700959

System Scanned (13)

System	Status/DTC
Engine-PGM FI	0
AT	0
ABS/TCS/VSA	1
SRS	0
Gauges	0
Electric Parking Brake	3
Body electrical	0
Parking Sensor	0
IMMOBI	0
EPS	2
Keyless access (RL)	0
PCU	0
Backup Control Unit	0

ADAS

DTC (6)

ABS/TCS/VSA (1 DTC)

DTC	Description	Status
61-11	Modulator-control unit power source circuit (IG) low voltage	Permanent DTC

Electric Parking Brake (3 DTCs)

DTC	Description	Status
C1120-96	Electric Parking Brake Switch Malfunction	Permanent DTC

U3003-16	Electric Parking Brake Control Unit Power Source Circuit (+B) Low Voltage	Permanent DTC
U0416-68	VSA System Malfunction	Permanent DTC

EPS (2 DTCs)

DTC	Description	Status
U0416-68	VSA System Malfunction	Permanent DTC
U3003-17	Battery Voltage High	Permanent DTC

I/M I/M readiness status

Fault codes	Status
MIL status	OFF
DTC	0

Monitor status	Status
----------------	--------

	MIS	Misfire monitoring	
	FUEL	Fuel system monitoring	
	CCM	Comprehensive component monitoring	
	CAT	Catalyst monitoring	
	HCAT	Heated catalyst monitoring	
	EVAP	Evaporative system monitoring	
	AIR	Secondary air system monitoring	
	O2S	Oxygen sensor monitoring	
	HTR	Oxygen sensor heater monitoring	
	EGR	EGR system monitoring	

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2021 Honda Vehicle Diagnostic Report

Vehicle Information

2021/Honda/HR-V
VIN: MRJRU5851MP010622
Path: Honda>Automatic
selection>MRJRU5851MP010622>GENERAL>HR-V>2021>Auto
scan>Engine-PGM FI>Live data

Odometer Reading: 99769 km
License Plate: --
Sub Model: GENERAL

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.32

Serial Number: VA9GR4C01193



Engine: 88%