



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **EMGRAND**

Date : **12/9/2026**

Plate No. : **931530**

Time : **10:45**

Model : **2025** Color : **GREY**

Type of Check : **Engine +gear+chassis+paint**

VIN: LB3F31S33SG007913

113215KM

Scratches + dents on body + service for interior decor & leather

Front left fender + rear right fender lower right body panel bend

Under the car scratches by stones + lower cover broken

Rear iron bumper bend

Change rear brake pads + AC compressor make sound

Thank you for choosing Golden Munich cars inspection

Paint :

Plastic kit + bonnet + rear body door

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

Geely Vehicle Diagnostic Report

Vehicle Information

--/Geely/4th generation Emgrand/4th generation Emgrand (2025 model)/

VIN: LB3F31S33SG007913

Odometer Reading: 113215km

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Version: V10.90

Serial Number: VA9GR4C01193

Repair Order Number:
VA9GR4C0119320260912103844434

System Scanned (11)

System	Status/DTC
EMS (Engine Management System)	 2
TCU (Transmission Control Unit)	 0
ESP(Electronic Stability Program)	 1
SRS (Supplement Restrain System)	 0
IPK (Instrument panel system)	 1
A/C (automatic air conditioning system)	 3
EPS(Electronic Power Steering system)	 0
GW (Gateway)	 2
BCM (Body Control Module)	 1
MMI(Multimedia system)	 1
TCM (Top Column Module)	 0

DTC (11)

EMS (Engine Management System) (2 DTCs)

DTC	Description	Status
P26CE00	Electronic water pump (engine) dry run	Read Codes/History DTCs
P26CB96	Engine electronic water pump controller internal fault	Read Codes/History DTCs

ESP(Electronic Stability Program) (1 DTC)

DTC	Description	Status
U015687	Lost communication with Multi Media Interface (MMI)	Read Codes/History DTCs

IPK (Instrument panel system) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U015687	Lost communication with multimedia interactive system	Read Codes/History DTCs
---------	---	-------------------------

A/C (automatic air conditioning system) (3 DTCs)

DTC	Description	Status
U300616	Controller input power voltage too low	Read Codes/History DTCs
U015687	Lost communication with Multi Media Interface (MMI)	Read Codes/History DTCs
B118371	air distribution motor is locked	Read Codes/History DTCs

GW (Gateway) (2 DTCs)

DTC	Description	Status
U300616	Control Module Input Power Low	Read Codes/History DTCs
U015687	Lost communication with Multi Media Interface (MMI)	Read Codes/History DTCs

BCM (Body Control Module) (1 DTC)

DTC	Description	Status
B100E13	Right turn light open or some bulb broken	Read Codes/Curren DTC

MMI(Multimedia system) (1 DTC)

DTC	Description	Status
U300616	Control Module Input Power Low	Read Codes/History DTCs

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Geely Vehicle Diagnostic Report

Vehicle Information

Geely/4th generation Emgrand/4th generation Emgrand (2025 model)
VIN: LB3F31S33SG007913
Path: Geely>Manual selection>4th generation Emgrand>4th generation Emgrand (2025 model)>Auto scan>EMS (Engine Management System)>Live data

Odometer Reading: 113215 km

License Plate: --

Sub Model: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV

Serial Number: VA9GR4C01193

Version: V10.90



Engine: 92%