



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : **URVAN**

Date : **12/9/2026**

Plate No. : **17651**

Time : **14:20**

Model : **2022** Color : **WHITE**

Type of Check : **Engine +gear+chassis+paint**

VIN: JN6BE6CS1N9426631

113346KM

Scratches + dents on body + plastic kit + body paint damage

Front bumper loose + service for interior leather

Steering hose leak + change rear shock absorber

Sound from differential

Thank you for choosing Golden Munich cars inspection

Paint:

No paint on body

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة موآتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخبيسة - قطر

Customer Service

+974 40082021

خدمة العملاء

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07/Nissan/NV350 Urvan/
VIN: JN6BE6CS1N9426631Odometer Reading: 113346km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912140918563

System Scanned (8)

System	Status/DTC
Engine	 0
Transmission	 0
ABS	 1
Air bag	 0
Meter/M&A	 0
Air pressure monitor	 0
BCM	 0
IPDM E/R	 0

DTC (1)

ABS (1 DTC)

DTC	Description	Status
C1143	Steering angle sensor circuit	Past

I/M readiness status

Fault codes	Status
MIL status	OFF
DTC	0
Monitor status	
Status	
 MIS	Misfire monitoring 
 FUEL	Fuel system monitoring 
 CCM	Comprehensive component monitoring 

	CAT	Catalyst monitoring	✓
	HCAT	Heated catalyst monitoring	⊘
	EVAP	Evaporative system monitoring	⊘
	AIR	Secondary air system monitoring	⊘
	O2S	Oxygen sensor monitoring	✓
	HTR	Oxygen sensor heater monitoring	✓
	EGR	EGR system monitoring	✓

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07-/Nissan/NV350 Urvan
VIN: JN6BE6CS1N9426631
Path: Nissan>Automatic selection>Auto scan>Engine>Live data

Odometer Reading: 113346 km
License Plate: -
Sub Model: E26

Customer Information

Name: -

Tel: -

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193



Engine 89.1