



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : PATROL	Date 13/9/2026
Plate No. : 897012	Time : 9:00
Model : 2023 Color : WHITE	Type of Check : Engine +gear+chassis+paint

VIN: JN8BY2NY6P9406919

355825KM

Change tyres + alignment

Scratches + dents on body + front glass broken + body paint damage

Step board damage + front bumper loose + cover upper tyre damage

Right 2 fender + rear right door bend + service for driver leather

Rust under the car & chassis + scratches by stones

Petrol cover tank bend + front iron bumper bend

Engine gasket + gearbox bell housing bolts + gearbox crankcase open before

Service for CHECK ENGINE (Engine misfire) + change engine & gearbox mounting

AC hose leak + change brake pads + rear differential mounting

Change arm bushes + shock absorber mounting + bonnet shock absorber

Service for drive shaft + differential

Please check attached diagnosis computer report

Paint :

Plastic kit + bonnet

All left side

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده

* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2022/08- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/08/Nissan/Patrol (AT)/
VIN: JN8BY2NY6P9406919Odometer Reading: 355825km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.40Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260913084810777

System Scanned (13)

System	Status/DTC
Engine	 3
Transmission	 0
ABS	 3
Air bag	 0
Meter/M&A	 0
Air pressure monitor	 1
BCM	 1
All mode AWD/4WD	 1
HVAC	 2
IPDM E/R	 0
Difference lock	 0
Sonar	 8
3-channel CAN gateway	 0

DTC (19)

Engine (3 DTCs)

DTC	Description	Status
P0303	Cycle 3 misfire	17 Time
P0300	Multi cylinder misfire	17 Time
P0430	TW catalyst sys-b2	2 Time

ABS (3 DTCs)

DTC	Description	Status
-----	-------------	--------

C1109	Battery voltage (abnormal)	Past
C1116	Stop lamp switch	Past
C1142	Pressure sensor circuit	Past

Air pressure monitor (1 DTC)

DTC	Description	Status
C1711	Tire pressure data signal from the rear left wheel tire pressure sensor cannot be detected.	Current

BCM (1 DTC)

DTC	Description	Status
B2562	Low voltage	Past

All mode AWD/4WD (1 DTC)

DTC	Description	Status
P181B	Incomplete self shutdown	111 Time

HVAC (2 DTCs)

DTC	Description	Status
B2631	Sunload sensor	Current
B2668	Pass sunload sensor	Current

Sonar (8 DTCs)

DTC	Description	Status
B2700	Corner sensor (left front)	39 Time
B2702	Corner sensor (right front)	39 Time
B2704	Corner sensor (left rear)	39 Time
B2706	Corner sensor (right rear)	39 Time
B2708	Center sensor (left rear)	39 Time
B270A	Center sensor (right rear)	39 Time
B270C	Center sensor (left front)	39 Time
B270E	Center sensor (right front)	39 Time

** I/M readiness status**

Fault codes	Status
MIL status	ON
DTC	3

Monitor status	Status
----------------	--------

	MIS	Misfire monitoring	✓
	FUEL	Fuel system monitoring	✓

2022/08- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/08-/Nissan/Patrol (AT)
VIN: JN8BY2NY6P9406919
Path: Nissan>Manual selection>Middle and near
east>Qatar>Patrol (AT)>Y62>2022/08->Auto scan>Engine>Live
data

Odometer Reading: 355825 km
License Plate: --
Sub Model: Y62

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.40

Serial Number: VA9GR4C01193



Engine gas ket open before.