



ميونخ الذهبي لفحص السيارات ذ.م.م

Golden Munich Cars Inspection W.L.L

فحص بالكمبيوتر لجميع انواع السيارة
Computerized Testing For All Kind of Cars



Car : URVAN	Date : 12/9/2026
Plate No. : 250044	Time : 12:30
Model : 2022 Color : WHITE	Type of Check : Engine +gear+chassis+paint

VIN: JN6BE6CS7N9426763

149474KM

Change tyres + alignment

Scratches + dents on body + front right door & body left side bend

Rear iron bumper bend

Gearbox crankcase open before + change engine mounting

Please check attached diagnosis computer report

Paint:

Rear body door

Check paint as per customer request

المركز غير مسؤول عن أي اضرار قد تظهر بالسيارة اثناء الفحص أو بعده
* Center is not responsible for any damage may show car of examination or Later

Munich Al Thahaby Vehicle Inspection W.L.L. its capital limits

ميونخ الذهبي لفحص السيارات ذ.م.م. حدودها رأس مالها

Salwa Road - Ain khaled - Qatar

+974 66338337

طريق سلوى - عين خالد - قطر

Mawater City - Rawdat Rashed - Qatar

+974 66332237

مدينة مواتر - روضة راشد - قطر

Al Kheesa Qatar

+974 66332237

الخيصة - قطر

Customer Service

+974 40082021

خدمة العملاء

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07/Nissan/NV350 Urvan/
VIN: JN6BE6CS7N9426763

Odometer Reading: 149474km
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193
Repair Order Number:
VA9GR4C0119320260912123704434

System Scanned (8)

System	Status/DTC
Engine	0
Transmission	0
ABS	3
Air bag	0
Meter/M&A	0
Air pressure monitor	0
BCM	1
IPDM E/R	1

DTC (5)

ABS (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past
C1143	Steering angle sensor circuit	Past
C1109	Battery voltage (abnormal)	Past

BCM (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

IPDM E/R (1 DTC)

DTC	Description	Status
U1000	CAN communication circuit	Past

I/M readiness status

Fault codes	Status
-------------	--------

MIL status OFF

DTC 0

Monitor status Status

	MIS	Misfire monitoring	✓
	FUEL	Fuel system monitoring	✓
	CCM	Comprehensive component monitoring	✓
	CAT	Catalyst monitoring	✓
	HCAT	Heated catalyst monitoring	⊘
	EVAP	Evaporative system monitoring	⊘
	AIR	Secondary air system monitoring	⊘
	O2S	Oxygen sensor monitoring	✓
	HTR	Oxygen sensor heater monitoring	✓
	EGR	EGR system monitoring	✓

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

2022/07- Nissan Vehicle Diagnostic Report

Vehicle Information

2022/07-/Nissan/NV350 Urvan
VIN: JN6BE6CS7N9426763
Path: Nissan>Automatic selection>Auto scan>Engine>Live data

Odometer Reading: 149474 km
License Plate: --
Sub Model: E26

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909EV
Version: V7.21

Serial Number: VA9GR4C01193



Engine: 88%