



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car :	MITSUBISHI PICKUP	Date :	30-09-26
Plate No. :		Time :	8:39 PM 106953KM
Model :	2021	Color :	WHITE
		Type of Check :	full check+paint

CHASSI: MMBMGU5H9MH005735

	front	rear	center	scanner check
right	OK	OK	OK	OK
left	OK	OK	OK	

Engine-Gear-Diffrentiell:

Engine: 87% valve cover gaskey leak+service valve lifter+oil pump+service engine
service timing belt

Gear: OK

Differential: OK

Body -Suspension-Notes:

body+kit plastic scratch+small dent+front plastic bumper broken+loose

under the car+chassi rust because of salty water+body rust+march r.side bend

A/C compressor make sound+service A/C+change tyre+alignmnet+service brake

service exhoust+over holl front suspension+change rear spring bush

change rear shock absorbar l.side leak+service electric car

Paint:

no body paint

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823



اف بي جي الالماني

FBG GERMANY

فحص بالكمبيوتر لجميع أنواع السيارات
Computerized Testing For All Kinds of Cars

Car : MITSUBISHI PICKUP	Date : 30-09-26
Plate No. : 317077	Time : 8:39 PM 106953KM
Model : 2021 Color : WHITE	Type of Check : فحص شامل+صينغ

شاصي: MMBMGU5H9MH005735

فحص الاسكانر	وسط	خلفي	امامي	
OK	OK	OK	OK	يمين
OK	OK	OK	OK	يسار

مكيينة+جير+دفرنش:

مكيينة: 87% كسكيت غطاء الصبايات ليك+سيرفس لفتر الصبايات+طرمبه الزيت+سيرفس للمكيينة
سيرفس قشاط الصدر

جير: OK

دفرنشات: OK

البدي-بوشات-ملاحظات:

البدي+كيت بلاستيك مجرحين+منقرين بسيط+صدام بلاستيك امامي مكسور+مرتخي

حلا اسفل السيارة+الشاصي بسبب مياه مالحة+البدي محلي+المارش يمين مطعوج

يوجد صوت في كمبرسور A/C+سيرفس A/C+تبديل توابر+ميزانية+سيرفس بريك

سيرفس الاكزوست+صيانة للهيئة الامامية+تبديل بوشات طيات خلفية

تبديل جنبينات خلفي يسار ليك+سيرفس للكهرباء السيارة

صينغ:

لا يوجد صينغ في البدّي

* المحل غير مسؤول عن اي اعطال قد تظهر بالسياره

* Center is not responsible for any damage may show car.



شارع سلوى تليفون: 66667239, 50783559 ص.ب: 90823 الدوحة - قطر

Salwa Road, Tel.: 66667239, 50783559 P.O. Box : 90823