تقرير المعاينة

Car Sticker	Y-16357	رقم الملصق Car Motors	SUZUKI	علامة المركبة
Chassis Number	MBHZF6C14PG248244	رقم الشاسيه Car brand	DZIRE	فئة المركبة
Milage	163,694.00	دادعلا Man.Year	2023	سنة الصنع

Engine - الماكينة		Gear - الجير		Chassis - الشاصي	
Engine service	سيرفيس ماكينة	Check Axels	تحقق من المحاور	Rear chassis (left) Head Dent/Repair	طعج/تعديل راس شاصي خلفي يسار
		Gear service	سيرفيس جير	Rear chassis (Right) Head Dent/Repair	طعج/تعديل راس شاصي خلفي يمين
				Rock hit.	ضرب حصا

Mechanichs - الميكانيك		Visual - النظري		Others - اخرى	
Repair Suspension System.	تصليح نظام التعليق	Front Accident.	حادث امامي	No Issues	لا يوجد ملاحظات
Check tire & Wheel alignment.	فحص توابر وعمل ميزانية	Rear Accident.	حادث خلفي		
Engine belt and bearings replacement.	تبديل سير الماكينة + البرينجات	Body Dents & Repair.	طعج في البودي + تصليحات في البودي		
Gear mount replacement.	تبديل كراسي جير	Body Scratches.	خدوش في الهيكل		
Engine mount replacement.	تبديل كراسي ماكينة				
Slight engine oil leak.	تهريب زيت ماكينة خفيف				
Brake service	سيرفيس بريك				
Airbag check	تشيك على الايرباق				

Notes Related to the Car - ملاحظات تخص المركبة

Full body paint	صبغ كامل

Terms for submitting a vehicle retrieval request	شروط تقديم طلب استرجاع المركبة

يتم التقديم على طلب ارجاع المركبة وفقا وحصرا عند اتباع الإجراءات أدناه

1- احضار فحص المركبة من مركزنا المعتمد فقط (كاشف لفحص السيارات) خلال مدة اقصاها 24 ساعة من تاريخ نقل الملكية.

2- يتم تقديم الطلب عن طريق خدمة العملاء (الدردشة) من داخل تطبيق مزاد قطر

3- يتم الموافقة على طلب ارجاع المركبة في الحالات االتاليه فقط لا غير في حال ما لم يتم الذكر في التقرير أعلاه.

1- وجود ضرر في الشاصي (لا يشمل اي اجزاء اخرى مرتبطة بالشاصي) مثل راس الشاصي او جسور الشاصي.

2- وجود عطل رئيسي في المحرك يمنع المركبة من التحرك في الطرقات بشكل طبيعي ما لم يتم ذكره في التقرير أعلاه.

3- وجود عطل رئيسي في ناقل الحركة يمنع المركبة من التحرك في الطرقات بشكل طبيعي ما لم يتم ذكره في التقرير أعلاه.

The vehicle return application is submitted exclusively by following the procedures below:

1-Bring the vehicle inspection from our authorized center only (Kashif Car insepction) within a maximum period of 24 hours from the date of transfer of ownership.

2-The application is submitted through customer service (chat).

3-Approval for vehicle return is granted only in the following cases unless mentioned otherwise in the above report:

Presence of damage to the chassis (excluding any other parts related to the chassis) such as the chassis head or chassis bridges.

The presence of a major engine malfunction prevents the vehicle from moving on the roads normally unless mentioned in the above report.

Presence of a major malfunction in the transmission preventing the vehicle from moving on the roads normally unless mentioned in the above report.

ەيونت

يرجى العلم أن هذا التقرير معد بصريا فقط ولا يجب الاعتماد عليه كمصدر معلومات نهائي.
تخلي شركة مزاد قطر صراحة أي مسؤولية عن دقة أو اكتمال البيانات الواردة في هذا الوثيقة.
يتم توفير هذا التقرير استنادًا إلى موافقة البائع ويتم إرفاقه هنا لأغراض توضيحية
ويعتبر البائع المسؤول الوحيد عن كل ما ذكر او لم يذكر في هذا التقرير.

The report is solely for visual reference and shouldn't be the main source of information. Mzad Qatar isn't liable for its accuracy or completeness, as it's based on the seller's approval for illustrative purposes. Buyers need to verify information independently before deciding, and only the seller is responsible for the report's content, whether mentioned or not.